
## DRAINAGE STRUCTURE IMPROVEMENT DETAIL LOCATION #3 STA. 825 + 00

## NOTE:

THE EXISTING STRUCTURE AT STATION 825+00 CONSISTS OF A 24" R.C.C.P. WITH A MEDIAN INLET. THE STRUCTURE IS IN FAIR CONDITION WITH THE FOLLOWING DEFICIENCIES. WHILE THE JOINT BETWEEN THE DOWNSTREAM END SECTION AND THE FIRST SECTION OF PIPE IS INTACT, THE NEXT JOINT UPSTREAM IS SEPARATED AND IS CAUSING A SINKHOLE IN THE FORESLOPE. ALSO, THE DOWNSTREAM END SECTION IS SILTED-IN APPROXIMATELY 18". THE DOWNSTREAM OUTFALL IS RESTRICTED BY SILTATION, TREES AND BRIGH

THE PROPOSED SCOPE OF WORK IS TO EXCAVATE TO AND SEAL THE SEPARATED JOINT WITH A CONCRETE COLLAR. THE SILTATION SHALL BE CLEANED OUT OF THE DOWNSTREAM END OF THE STRUCTURE. THE DOWNSTREAM CHANNEL SHALL BE CLEANED AND GRADED AWAY FROM THE STRUCTURE TO PROVIDE POSITIVE DRAINAGE. THE TREES AND BRUSH SHOULD BE REMOVED AND PROPERLY DISPOSED OF. THE COST OF EXCAVATION REQUIRED TO PLACE THE CONCRETE COLLAR IS INCLUDED IN THE VARIOUS PAY ITEMS AND NO ADDITIONAL COMPENSATION WILL



FOOT

6

Z0014800 Culvert To Be Cleaned

