

CRACK ARRESTOR HOLE DETAIL

Note:

Locate crack tip using liquid dye penetrant or magnetic particle testing. Drill $^{13}_{16}$ " min. ϕ Crack Arrestor hole at the crack tip. After crack arrestor hole has been drilled, dye penetrant or magnetic particle testing shall be used to verify that the drilled hole has captured the crack tip. A high strength bolt with washers shall be installed, when possible, in the crack arrestor hole.

All work and material required to drill the holes shall be included in the pay item "Structural Steel Repair".

TABLE FOR LOCATIONS OF CRACK ARRESTOR HOLE DRILLING

·					
Span	Member	Location	Deficiency		
14	F.B. 0	Pier 13, South End	6" Crack, Web to Flange Weld		
14	F.B. 0	Pier 13, North End	2 ¹ 2" Crack in Web		
14	F.B. 0'	Pier 14, North End	1" Crack in Web		
18	Girder J	Pier 17	4 ¹ 2" Crack, Web to Bott. Flange Weld		



MEDIAN PARAPET JOINT SEALER DETAILS

Note:

The existing longitudinal joint at the median parapets shall be cleaned and sandblasted prior to the installation of the Backer Rod and the Silicone Bridge Joint Sealer. The new Bridge Joint Sealer shall be installed on the entire length of the bridge. See special provision "Silicone Bridge Joint Sealer".

Span	Member	Location	Deficiency		
9	Girder H	W. Splice, Bott. R	1 Loose Bolt		
12	Girder J	W. Splice	1 Loose Bolt		
13	Cross Girder	Pier 13, below Girder D	1 Missing Bolt		
14	Lower Lateral Bracing	FB. 3, below Stringer 6	1 Loose Bolt		
14	Lower Lateral Bracing	10′ from FB. 7, Pan. 7′	1 Missing Bolt		
14	Catwalk	FB. 6', P.P. 5'	1 Missing Bolt		
14	FB. 1'	Stringer 2, Pan. O'	1 Loose Bolt		
14	Lower Lateral Bracing	FB. O', below Stringer 3 T. Conn. R	5 Loose Bolts & 1 Missing Nut		
14	Wind Bracing Strut	3′ N. of € of FB. O′ W. Fa. below FB. O′	1 Broken Bolt at Sliding Connection		
15	Cross Frame	3rd C.F. from Pier 14 btwn. Gir. H & J, Gir. H Bott Conn.	3 Loose Bolts		
16	Girder G	Splice E. of Pier 15, at Bottom Flange P	1 Loose Bolt		
16	Cross Frame 3rd C.F. E. of Pier 15 btwn. Girders G & H at Gir. H		3 Loose Bolts		
16	Cross Frame	4th C.F. E. of Pier 15 btwn. Girders G & H at Gir. H	3 Loose Bolts		
17	Cross Frame	4th C.F. E. of Pier 17 btwn. Girders H & J at Gir. H	2 Loose Bolts		
17	Cross Frame	3rd C.F. E. of Pier 17 btwn. Girders H & J at Gir. H	1 Loose Bolt		
17	Cross Frame	2nd C.F. E. of Pier 17 btwn. Girders G & H at Gir. H	2 Loose Bolts		
<i>18, 1</i> 9	Bearing	Girder F & G at Pier 18	Missing Bolt conn. Top Sole Æ to Brg.		
21	Bearing	Girder J at Pier 20	Missing Shoulder Bolt Nut for Pin		
25	Cross Frame	1st C.F. E. of Pier 24 btwn. Girders H & J at Gir. H	6 Loose Bolts (3 top, 3 bott.)		

Note:

item ''Structural Steel Repair''.

TABLE FOR LOCATIONS OF SILICONE CAULKING

Span	Member	Location	Deficiency		
14	South Arch	Top chamber at splice plate, btwn. T4 & T5	Leaking water causing rust		
14	South Tie	2nd & 6th splice plate west to east	Leaking water causing P.R.		
14	South Arch	Pier 14, where tie connects to arch	Gap letting water in, plugged drain holes need to be unplugged.		

Note:

Surface preparation in advance of silicone caulking shall entail the removal of rust from the surface to be caulked. At a minimum, wire brushes and compressed air shall be utilized to prepare a bondable surface for the silicone caulking. The silicone caulk shall be 100% silicone caulk with a cured color of clear. All drain holes that are plugged shall be unplugged. All work and material necessary to complete the silicone caulking at the locations noted in the table shall be included in the pay item "Structural Steel Repair".

DESIGNED - Marcus K. Christensen	EXAMINED	Jayne F. Schiff	DATE - NOVEMBER 23, 2011		REPAIR DETAILS	F.A.I. RTE.	SECTION	COUNTY TOTAL SHEET SHEETS NO.
CHECKED - Irvin J. Lopez		ACTING ENGINEER OF STRUCTURAL BERVICES		STATE OF ILLINOIS	SN 081-0106	280	(81-1B)M-2	ROCK ISLAND 30 20
DRAWN - Kyle M. Steffen	PASSED		REVISED	DEPARTMENT OF TRANSPORTATION		_		CONTRACT NO. 64F22
CHECKED - MKC IJL		ACTING ENGINEER OF BRIDGES AND STRUCTURES	REVISED		SHEET NO. 4 OF 14 SHEETS		ILLINOIS FED. A	AID PROJECT

TABLE OF BOLT REPAIRS

Loose bolts shall be removed and then replaced with bolts meeting the Standard Specifications. New bolts shall match the diameter and length of the existing bolts. New bolts shall be ASTM 325 High Strength Bolts. All work and material necessary to complete the bolt replacement as noted in the table shall be included in the pay

BILL OF MATERIAL

ITEM	UNIT	QUANTITY
Silicone Joint Sealer	Foot	4193
Structural Steel Repair	Pound	90