JOINT REPAIR AT NORTH ABUTMENT S.N. 020–0050

| CONTRACT | NO. 70593 |
| F.A.P | SECTION | COUNTY | TOTAL | SHEET | NO. 322 | * DEWITT | 35 | 8 |
| STA. | TO STA. | ST

*(52BR-1 & 53R-B)BJR

SHEET 4 OF 8

BAR LIST

Bar No. Size Length Shape

Reinforcement bars designated (E) shall


Hatched areas indicates Concrete Removal.


See Sheet 5 of 8 for Proposed Joint Section.

See Sheet 8 of 8 for Section Thru Parapet.

be epoxy coated.

#6 24'-0"





EXISTING PARTIAL PLAN Joint at North Abutment

PROPOSED PARTIAL PLAN

Joint at North Abutment

Concrete Removal

> Approach Slab Repair

Note: As built standards show the existing thicknesses of the approach pavement to be 15" for the passing lane and 10" for the median shoulder.

ILLINOIS DEPARTMENT OF TRANSPORTATION JOINT REPAIR AT NORTH ABUTMENT

F.A.P. ROUTE 322
SECTION (52BR-1 & 53R-B)BJR
DEWITT COUNTY
S.N. 020-0050

SCALE: NA DRAWN BY: JRP
DATE: 11/06/06 CHECKED BY: