

red. ROAD DIST. NO. 7		ILL1HOIS	FED. AID PROJECT-]	
F.A.P. 782	115BR-2	Hardin		83	60	<i>1</i> 5 s	HEETS
ROUTE NO.	SECTION	COUNTY		TOTAL SHEETS	SHEET NO.	SHEE	т но.

14

NOTES

See Sheet 8 of 15 for Sections Thru Abutment views and additional reinforcement details for abutment Hatch-Block and Approach Footing.

The existing abutment bearing seat is to be inpected by the Engineer after deck beam removal. Deteriorated concrete areas shall be repaired if deemed necessary using Structural Repair of Concrete (Depth equal to or less than 5". Concrete Sealer shall be applied to Concrete Repair areas. Çost included in Concrete Repair item.

Abutment Structural Repair of Concrete areas and Crack Repair lengths are estimated from a 10/24/2007 inspection.

REPAIR LEGEND

ŘŽ

Requires Structural Repair of Concrete (Depth Equal to or less than 5'')

Requires Epoxy Crack Injection

BILL OF MATERIAL - EAST ABUT.

BAR	NO.	SIZE	LENGTH	SHAPE
h2(E)	2	#4	12'-6''	
h3(È)	2	#4	15'-10''	
†(E)	31	#4	2'-9''	
v(E)	20	#5	3'-4''	
w(E)	4	#4	12'-6''	
w1 (E)	4	#4	15'-10''	
Reinforcement Bars, Epoxy Coated			Pound	240
Epoxy Crack Injection			Foot	4
Concrete Structures			Cu. Yd.	2.7

HAMPTON, LENZINI & RENWICK, INC. CIVIL & STRUCTURAL ENGINEERS LAND SURVEYORS

3085 STEVENSON DRIVE, SUITE 201 SPRINGFIELD, ILLINOIS 62703 (217) 546-3400

ELGIN	•	SPRINGFIELD
12-98-00	16-i	DATE: 01/18/08
CHECKED:	P.S.L.	DRAWN: D.T.M.

IL. ROUTE 1 OVER BRANCH OF ROCK CREEK F.A.P. ROUTE 782 / SECTION 115BR-2 HARDIN COUNTY STATION 1015+72

EAST ABUTMENT

STRUCTURE NO. 035-0003