# STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION

# NOTES

1'x1' Repair

**ELEVATION** (Looking West)

1'x3' Repair


See Sheet 10 of 16 for Sections Thru Abutment views and additional reinforcement details for abutment Hatch-Block.

The existing abutment bearing seat is to be inspected by the Engineer after deck beam removal. Deteriorated concrete areas shall be repaired if deemed necessary using Structural Repair of Concrete (Depth equal to or less than 5"). Concrete Sealer shall be applied to Concrete Repair areas. Cost included in Concrete Repair item.

Abutment Structural Repair of Concrete areas are estimated from a 10/24/2007 inspection.




Contract #78030



## SIDE RETAINER

Equivalent rolled angle with stiffeners will be allowed in lieu of welded plates.



 $\[ \underline{\ell} \] \] 1^l_2 '' \phi x 18'' \ Galv. Anchor Bolts \ (Grade 36) with 3'' x 3'' x 5_{16}'' \ P_c$ washer under nut

# EXTERIOR BEAM RETAINER DETAILS

Cost of Side Retainer, Anchor Bolts & accessories are included with Precast Prestressed Concrete Deck Beams.

The side retainer shall be galvanized after shop fabrication according to AASHTO M111.

Anchor bolts shall be ASTM F1554 all-thread (or an Engineer-approved alternate material) of the grade(s) and diameter(s) specified. ASTM A307 Grade C anchor bolts may be used in lieu of ASTM F1554 Grade 36

Anchor bolts for side retainers may be cast in place or installed in holes drilled after members are in place.

Fill  $l_8^{\prime\prime}$  gap with shim  $I\!\!\!E$  to provide temporary lateral support until shear keys have been grouted and concrete wearing surface as been placed.

# REPAIR LEGEND

2"\$ Hole

Requires Structural Repair of Concrete (Depth Equal to or less than 5")

Hatched Area indicates Exist, Concrete to be removed. Paid for as Concrete Removal.

## BILL OF MATERIAL - WEST ABUT.

			·······	<del></del>
BAR	NO.	SIZE	LENGTH	SHAPE
h(E)	2	#4	14'-9''	
$h_I(E)$	2	#4	17'-9''	
v(E)	33	#5	3'-4"	
Concrete Structures			Cu. Yd.	2.0
Reinforcement Bars, Epoxy Coated			Pound	160
Concrete Removal			Cu. Yd.	1.6
Bar Splicers			Each	2
Structural Repair of Concrete			Sq. Ft.	5.0
Asbestos Bearing Pad Removal			Each	28

HAMPTON, LENZINI & RENWICK, INC.
CIVIL & STRUCTURAL ENGINEERS
LAND SURVEYORS

3085 STEVENSON DRIVE, SUITE 201 SPRINGFIELD, ILLINOIS 62703 (217) 546-3400

ELGIN • SPRINGFIELD

ROJECT NUMBER: 12-52-0007-i DATE: 04/02/08 DESIGNED: P.S.L. CHECKED: M.D.C. DRAWN: D.T.M.

IL. ROUTE 146 OVER BELL POND F.A.P. ROUTE 885 / SECTION IIIBR-1 JOHNSON COUNTY STATION 513+00 STRUCTURE NO. 044-0022

WEST ABUTMENT

Concrete Removal

1'x1' Repair

