

Note: Expansion Dams not shown for clarity.



STRINGER END REPAIR AT EXPANSION DAM PIER 8 AND 24 - STRINGER LINES 1 AND 8 TYPICAL REMOVAL ELEVATION

Note

Remaining exposed shear connectors damaged as a result of construction shall be replaced, at the contractor's expense to the satisfaction of the engineer.



STRINGER END REPAIR AT EXPANSION DAM PIER 8 AND 24 - STRINGER LINES 2 AND 7 TYPICAL REMOVAL ELEVATION

DESIGNED YSS

CHECKED ACK


DRAWN PRC


CHECKED YSS

09/17/09



STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION







STRINGER END REPAIR AT EXPANSION DAM PIER 8 AND 24 - STRINGER LINES 1, 2, 7 AND 8 TYPICAL ELEVATION

Note:

Load carrying components designated "NTR" shall conform to the supplemental requirement for Notch Toughness, Zone 2.




SECTION A-A



BEARING P

<u>DIAPHRAGM CONNECTION AT EXPANSION DAM</u> <u>PIER 8 AND 24 - STRINGER LINES 3 AND 6</u>



SECTION B-B Stringer No. 1 & 8 shown, Stringer No. 2 & 7 similar

For General Notes, see Sheet No. 3 of 33.
For Splice details, see Sheet No. 14 of 33.
For deck removal, see Sheet No. 23 of 33.
For Expansion Dam details, see Sheet No. 29 of 33.
Two ¹₈" adjusting shims shall be provided for each bearing in addition to all other plates or shims and placed as shown on bearing details.

SECTION C-C

BILL OF MATERIAL

Item	Unit	Total*
Structural Steel Repair	Pound	209,500

^{*} For all stringer end repairs.

STRINGER END REPAIR DETAILS - 1 I-80 OVER MISSISSIPPI RIVER

STRUCTURE NO. 081-0011

SHEET NO. 11	F.A.I. RTE.	SECTION							CC	UNTY	TOTAL SHEET	SHEET NO.
	80	(81-1B)M-4							ROCK	ISLAND	75	38
33 SHEETS	SN 081-0011							CON	TRACT	NO. 6	4F31	
	FED. RO	DAD DIS	T. NO	. 7	IL	LINOIS	FED.	AID	PRO	JECT		