STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION




SHEET 10 6

SHEET NO. 2

5 SHEETS

Contract Number: 62957




PULLING DEVICE


PARTIAL PLANS

SUGGESTED BEAM STRAIGHTENING METHODS

PUSHING DEVICE

Straightening force shall be maintained on all load transfer blocking during beam straightening.






SECTION B-B


DESIGNED P.S.J.	November 9, 2005
CHECKED A.T.H.	EXAMINED John a. Morris
DRAWN Drew Christopher	PASSED Calph E. andersa
CHECKED P.S.J. / A.T.H.	ENGINÉER OF BAIDGES AND STRUCTURES

REP-1 1-14-2005




SUGGESTED VERTICAL STRAIGHTENING DETAIL

(To correct flange rotation.)



GRINDING DETAIL

Grind existing nicks, gouges and shallow cracks in the damaged beams as detailed. Ground surfaces shall be inspected for cracks using magnetic particle testing prior to initiating any beam straightening operations. Any cracks that cannot be removed by grinding approximately ${}^{l}_{4}{}^{\prime\prime}$ deep shall be identified and reported to the Bureau of Bridges and Structures for further disposition. Ground surfaces shall be spot cleaned and painted with an aluminum epoxy mastic primer followed by a finish coat to match the color of the existing beam. Cost of grinding, testing and spot painting included with Beam Straightening.



SUGGESTED VERTICAL STRAIGHTENING DETAIL

(To correct localized vertical flange deformations.)

* Edge of plate shall line up with edge of deformation.

Note:

Number

Braces and jack assembly shall be placed on same side of web. Bent bottom flange shall be straightened before starting any horizontal straightening operations.



EXISTING DEFORMATION TO BE STRAIGHTENED

(Looking West) (Approximate max. deflections)

DEFORMATION TABLE Deflected length of beam to be straightened is approximately "L". Dimensions 14" 10'-0'

BEAM STRAIGHTENING DETAILS CHURCH STREET / I-94 COOK COUNTY SN 016-0825