
## DRAINAGE STRUCTURE IMPROVEMENT DETAIL LOCATION #6 STA. 858 + 38 S.N. 057–8556

1

LOC.#6 STA.858+38		
ITEM# AND DESCRIPTION	UNIT	QUANTITY
21400100 Grading and Shaping Ditches	FOOT	20
28000305 Ditch Check Temporary	FOOT	10
28100107 Stone Rip Rap Class A4	SQ YD	29.8
28200200 Filter Fabric	SQ YD	29.8

THE EXISTING STRUCTURE AT STATION 858+38 CONSISTS OF A 36" R.C.C.P. WITH CAST IN PLACE END SECTIONS. THE STRUCTURE IS IN GOOD CONDITION BUT THE DOWNSTREAM CHANNEL HAS EXPERIENCED SCOUR AND THE TOEWALL IS EXPOSED.

THE PROPOSED SCOPE OF WORK IS TO REGRADE THE DOWNSTREAM CHANNEL AND PROTECT IT WITH A TREATMENT OF RIPRAP WITHIN THE R.O.W.



FILE NAME =	USER NAME = hoganbj	DESIGNED - BJM	REVISED -		DRAINAGE STRUCTURE IMPROVEMENT DETAIL LOCATION #6 STA. 858 + 38		F.A.I.	SECTION	COUNTY	TOTAL	SHEET
c:\pw_work\pwidot\hoganbj\dØl5834Ø\D57Ø	550-sht-sm struct det.dgn	DRAWN -	REVISED -	STATE OF ILLINOIS			74	(57-20(1),21,22)RS-3	McLean	150	56
	PLOT SCALE = 40.00000 '/ IN.	CHECKED -	REVISED -	DEPARTMENT OF TRANSPORTATION	LUCATION #0 51A. 838 + 38						70550
	PLOT DATE = 10/21/2010	DATE - 09/23/10	REVISED -		SCALE: 1" = 20'	SHEET NO. OF SHEETS STA. TO STA.		ILLINOIS FED. A	ID PROJECT		
			•	•			•				