
SUBSTRUCTURE REPAIR DETAIL SN 098-0052 SOUTH ABUTMENT (LOOKING SOUTH)



SN 098-0052 SOUTH ABUTMENT (LOOKING SOUTH)

ITEM	QUANTITY	
(*) STRUCTURAL REPAIR OF CONCRETE =< 5"	41.5 (SQ FT)	
(*) STRUCTURAL REPAIR OF CONCRETE > 5"	8.0 (SQ FT)	
TEMPORARY SHORING AND CRIBBING	1 (EACH)	

(*) THIS IS AN ESTIMATED QUANTITY. THE ACTUAL LOCATION OF DELAMINATED AREAS AND QUANTITIES WILL BE DETERMINED BY THE RESIDENT ENGINEER IN THE FIELD.

<u> </u>	JACKING AND	CRIBBING LOCATION
	DELAMINATED	AREA > 5"
	DELAMINATED	AREA =< 5"

1							F.A.U. SECTION COUNTY CHEETS NO
ļ,	ILE NAME :	USER NAME : dosedd	DESIGNED	REVISED -		SUBSTRUCTURE REPAIR DETAIL	RIE, STALL OF THE
1,	HE HE erioge SPL+D/ebjectiff//ecours SH 89	8-6051 & SN 898-8052\C468\8287713-sht-cove	ORAWN -	REVISEO -	STATE OF ILLINOIS	SN 098-0052 SOUTH ABUTMENT (LOOKING SOUTH)	5571 D2 BRIDGE REPAIR 2014-2 WHITESIDE 33 10
		PLOT SCALE = 100,0000 '/ in.	CHECKEO	REVISED -	DEPARTMENT OF TRANSPORTATION	CONT. CUTCT OF SUCCESS STA TO STA	CONTRACT NO. 64J92
1)n(suit	PLOT DOTE : Wed Age 30 08:02:38 2014	DATE -	REVISED -		SCALE: SHEET OF SHEETS STA. 10 STA.	TREMOISTIED, AID PROJECT