



ELEVATION - NW ABUTMENT
Looking West



ELEVATION - NE ABUTMENT


Looking East



<u>ELEVATION</u>

<u>NW ABUTMENT SOUTH WINGWALL</u>


Outside Face



ELEVATION

NW ABUTMENT NORTH WINGWALL


Outside Face



ELEVATION

NE ABUTMENT SOUTH WINGWALL

Outside Face



ELEVATION

NE ABUTMENT NORTH WINGWALL

Outside Face

BILL OF MATERIAL

				IT	ЕМ							UNIT	TOTAL
Structural	Repair	Of	Concrete	(Depth	Equal	To	0r	Less	Than	5	Inches)	Sq.Ft.	36
-													

<u>LEGEND:</u>



Spalled or unsound concrete

NOTES:

 Areas of proposed abutment repairs are estimated. Actual type, location and dimensions of abutment repairs are to be determined by the Engineer during construction.

	DESIGNED - PCA	REVISED -	
USER NAME = Isupencheck	DRAWN - LK	REVISED ~	
PLOT SCALE = 1:1	CHECKED - MEA	REVISED -	
PLOT DATE = 19-JAN-2011	DATE - 1/21/2011	REVISED -	
FILE NAME = IP_PWP:dms34565\Ø99Ø	Ø61-6ØM66-ØØ6-ABUT.DGN		



STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION

ABUTMENT REPAIRS
WESTBOUND FAI-80 OVER RAILROADGARDNER STREET
STRUCTURE NO. 099-0061
SHEET NO. S-6 OF 14 SHEETS