

FURNISHING & INSTALLING PROPERTY MARKERS SURVEY MONUMENT COVER ASSEMBLY			
STATION	OFFSET	DESCRIPTION	
1009+20.17	0'	P. T. FOUND BRASS IDOT DISK IN PCC CORRUGATED MEDIAN	1
1010+60.25	0'	P. C. FOUND BRASS IDOT DISK IN RAISED CONCRETE MEDIAN	1
1023+59.68	0'	P. T. DISK APPEARS TO BE GONE -NEAR BROKEN UP MEDIAN AND INLET AREA	1
1031+44.58	0'	P. C. FOUND BRASS IDOT DISK FLUSH WITH PCC PAVEMENT	1
1037+31.54	0'	P. T. FOUND BRASS IDOT DISK IN PCC CORRUGATED MEDIAN	1
1043+10.89	0'	P. C. FOUND BRASS IDOT DISK IN PCC CORRUGATED MEDIAN	1
1047+99.82	0'	P. T. FOUND BRASS IDOT DISK IN PCC CORRUGATED MEDIAN	1
1056+12.49	0'	FOUND I. P. WITH YELLOW CAP - FLUSH @ INTERSECTION 105 & BRUSH COLLEGE ROAD	1
1065+20.11	0'	P. C. FOUND BRASS IDOT DISK IN PCC CORRUGATED MEDIAN	1
1070+91.20	0'	P. T. FOUND BRASS IDOT DISK IN PCC CORRUGATED MEDIAN	1
1072+86.60	0'	P. C. FOUND BRASS IDOT DISK IN PCC CORRUGATED MEDIAN	1
1087+61.47	0'	P. T. FOUND BRASS IDOT DISK IN PCC PAVEMENT TURN LANE	1
1127+86.37	0'	P. C. FOUND BRASS IDOT DISK IN PCC CORRUGATED MEDIAN	1
1151+46.45	0'	P. T. FOUND BRASS IDOT DISK IN PCC PAVEMENT TURN LANE	1
TOTAL			15