



ELEVATION - N.W. WINGWALL

ELEVATION - NORTH ABUTMENT
(North Abut. - Looking North)

ELEVATION - N.E. WINGWALL








ELEVATION - S.E. WINGWALL

ELEVATION - SOUTH ABUTMENT
(South Abut. - Looking South)

ELEVATION - S.W. WINGWALL



STRUCTURAL REPAIR OF CONCRETE *TABLE*

Abutment Corner	Repo	Repair			
	Wingwall		Abutment		Area
	Α	В	С	D	Sq. Ft.
Northeast	1'-0''	6'-0''	2'-6"	4'-0''	16.0
Northwest	4'-0''	3'-0''	2'-6"	6'-0''	27.0
Southeast	1'-0''	3'-0''	2'-6''	4'-0''	13.0
Southwest	1'-0''	3'-0''	2'-6"	5'-0''	<i>1</i> 5.5

<u>LEGEND</u>



Structural Repair of Concrete (Depth $\leq 5''$)

BILL OF MATERIAL

Item	Unit	Quantity		
Structural Repair of Concrete (Depth $\leq 5''$)	Sq. Ft.	72		

ISOMETRIC VIEW AT ABUTMENT CORNER

		1							
DESIGNED - <u>Jos</u> ue Ortiz-Varela	EXAMINED	Jayme F. J. J.M.	DATE - MARCH 24, 2014		STRUCTURAL REPAIR OF CONCRETE	F.A.P.	SECTION	COUNTY SHE	TOTAL SHEET
CHECKED - <u>Mes</u> eret Sima		ACTING ENGINEER OF BRIDGE DESIGN		STATE OF ILLINOIS		322	54B-3, 54B-2	DEWITT 8	89 54
DRAWN - h.t. duong	PASSED	& Carl Princer	REVISED	DEPARTMENT OF TRANSPORTATION	STRUCTURE NO. 020-0046	_		CONTRACT NO	NO. 70606
CHECKED - <u>JOV</u> /MS/GRA	A	ACTING ENGINEER OF BRIDGES AND STRUCTURES	REVISED		SHEET NO. 10 OF 10 SHEETS		ILLINOIS FED.	AID PROJECT	