

REPLACEMENT DOWEL DETAIL

Stainless Steel in accordance with Article 1006.31(b)

Cummins	JOB = 2207	DESIGNED	M.D.C.
Engineering	FILE = 2207rail.dgn	CHECKED	A.A.N.
Corporation	DATE = 2/9/2011	DRAWN	Т.S.H.
Civil and Structural Engineering		CHECKED	M.D.C.

\* See Railing Restoration Note 2.

other hardware required to reset the rail elements shall not be measured

seperately but shall be included in the cost of the railing work.

## RAILING DETAILS VACHEL LINDSAY BRIDGE REHABILITATION LONG BAY DRIVE OVER LAKE SPRINGFIELD SPRINGFIELD. ILLINOIS

F.A.U. SECTION				COUNTY		TOTAL SHEETS		SHEET NO.	
8003	09-0046	9-00-BR			SANGAMON	4	36		31
CITY OF SPRINGFIELD				CONTRACT NO A					
FED. RO	AD DIST. NO.	ILLINOIS	FED.	AID	PROJECT	Č.	3	5	46