CONTRACT NO.								
62584, 62585, 62586, 62589, 62693, 62694, 62695	4							

REFERENCE

EXISTING

156 of 290

VERIFIED UTILITY INFORMATION	VERIFIED	UTILITY INFORMATION

TEST HOLE #	SIZE & 1	PYPE	NORTHING	EASTING	OFFSET	TOP OF UTILITY	EXISTING CUT	REFERENCE GROUND ELEVATION	COMMENTS		
165	24"	G	1858583.099	1177452.100	148.05 RT	-2.91'	6.08'	3.18'	SUE QUALITY LEVEL "A		
166	24"	G	1858582.607	1177422.881	118.82 RT	-7.96'	11.04'	3.08'	SUE QUALITY LEVEL "A		
167	24"	G	1858581.829	1177388.290	84.23 RT	-11.42'	5.64'	-5.78'	SUE QUALITY LEVEL "A		
168		G	1858576.435	1177169.958	73.59 LT	-14.41'	7.92'	-6.49'	SEE NOTE		
169A		G	1858575.515	1177148.755	94.81 LT	-8.73'	5.63'	-3.10'	SEE NOTE		
169B	8 <b>"</b> ·		1858574.341	1177148.755	94.81 LT	-7.34'	4.24'	-3.10'	SUE QUALITY LEVEL "A		
170	24"	G	1858574.341	1177125.527	118.07 LT	1.84'	4.35'	6.19'	SUE QUALITY LEVEL "A		
171	24"	G	1858573.831	1177107.217	136.38 LT	5.50'	5.82'	11.32'	SUE QUALITY LEVEL "A		
172	36"	E	1859349.450	1177086.590	133.62 LT	-2.77'	10.34'	7.57'	SUE QUALITY LEVEL "A"		
173	36"	E	1859349.210	1177115.830	104.39 LT	-5.89'	4.92'	-0.97'	SUE QUALITY LEVEL "A		
174	4 — BT 1859189.980 1177120.790			1177120.790	104.24 LT	-13.77'	12.58'	-1.19'	SUE QUALITY LEVEL "A		
175		BT	1859187.890	1177093.060	132.02 LT	SEE NOTE	9.12'	4.53'	CLEARANCE ONLY		
176	36"	E	1859357.690	1177382.160	100.06 RT	-11.29'	4.45'	-6.84'	SUE QUALITY LEVEL "A		
177	*******	E	1859358.400	1177405.990	123.90 RT	-10.32'	10.06'	-0.26'	SUE QUALITY LEVEL "A		
178		T	1859198.040	1177390.570	103.95 RT	-21.35'	12,85'	-8.50'	SUE QUALITY LEVEL "A		
179		E	1859345.500	1177059.620	160.69 LT	SEE NOTE	15.15'	16.93'	CLEARANCE ONLY		
180	36" (	G	1851291.10	1177413.23	80.62 LT	-9.95	6.63	-3.32	SUE QUALITY LEVEL "A		
181	36" (	G-	1851290.85	1177418.67	75.19 LT	-9.70	6.38	-3.32	SUE QUALITY LEVEL "A		
182	36" (	G	1851297.11	1177630.28	136.52 RT	-8.83	5.89	-2.94	SUE QUALITY LEVEL "A		
MAN HOLE #											
183	24" (	G	1851285.94	1177708.75	45.04 RT	4.76	4.16	8.92	Elev. taken from RIM of MH		
184	12" (	3	1851278.82	1177708.69	44.77 RT	4.39	4.52	8.91	Elev. taken from RIM of MH		
TEST HOLE #	SIZE & 1	TYPE	NORTHING	EASTING	OFFSET	TOP OF UTILITY	EXISTING CUT	REFERENCE GROUND ELEVATION	COMMENTS		
185	72"	ВТ	1877424.23	1176032.38	61.60 LT	-3.79	2.70	-1.09	SUE QUALITY LEVEL "A		
186	66"	вт	1877416.11	1175712.30	66.43 RT	-8.51	5.85	-2.66	SEE NOTE		

HOLE #	SIZE & TYPE	NORTHING	EASTING	OFFSET	UTILITY	CUT	GROUND ELEVATION	COMMENTS		
187	W	1880442.920	1175949.580	65.37' RT	3.59'	8.43'	12.02'	SEE NOTE		
188	16" BT	1880464.590	1175947.690	64.06' RT	6.63'	5.31'	11.94'	SUE QUALITY LEVEL "A"		
189	24" W	1880443.800	1175999.780	115.57' RT	7.85'	7.83'	15.68'	SUE QUALITY LEVEL "A"		
190	— W	1880442.870	1175973.130	88.91' RT	3.81'	10.10'	13.91'	SEE NOTE		
191	16" BT	1880465.830	1175973.580	89.98' RT	9.59'	4.42'	14.01'	SUE QUALITY LEVEL "A"		
192	16" BT	1880464.890	1175999.080	115.44' RT	10.21'	5.35'	15.56'	SUE QUALITY LEVEL "A"		
193	16" BT	1880456.000	1175630.210	61.54' LT	5.65'	8.94'	11.59'	SUE QUALITY LEVEL "A"		
194	16" BT	1880454,690	1175603.520	88.25' LT	5.44'	8.66'	14.10'	SUE QUALITY LEVEL "A"		
195	— ВТ	1880453.540	1175575.610	116.18' LT	4.75'	12.13'	16.88'	SEE NOTE		
196	24" W	1880435.180	1175604.240	88.06' LT	6.76'	7.24'	14.00'	SUE QUALITY LEVEL "A"		
197	24" W	1880435.160	1175579.320	112.97' LT	11.06'	5.48'	16.54'	SUE QUALITY LEVEL "A"		
198	36" G	1883748.370	1175516.740	86.01' LT	1.10'	7.08'	8.18'	SUE QUALITY LEVEL "A"		
199	36" G	1883747.800	1175488.980	113.78' L/T	6.36'	8.62'	14.98'	SUE QUALITY LEVEL "A"		
200	36" G	1883758.000	1175883.780	89.15' RT	-1.07'	5.96'	4.89'	SUE QUALITY LEVEL "A"		
201	36" G	1883758.190	1175903.970	109.34'RT	4.06'	6.58'	10.64'	SUE QUALITY LEVEL "A"		
202	36" W	1883741.550	1175904.750	109.67'RT	4.82'	5.74'	10.56'	SUE QUALITY LEVEL "A"		
203	36" W	1883730.260	1175489.640	113.59' LT	8.72'	6.25'	14.97'	SUE QUALITY LEVEL "A"		
204	36" W	1883731.680	1175518.680	84.53' LT	1.69'	5.90'	7.59'	SUE QUALITY LEVEL "A"		
205	36" W	1883740.460	1175883.620	88.52' RT	-3.96'	8.26'	4.30'	SUE QUALITY LEVEL "A"		
206	36" W	1883731.390	1175553.040	50.19' LT	-5.51'	6.13'	0.62'	SUE QUALITY LEVEL "A"		
207	BT	1884487.410	1175842.900	67.99' RT	-6.61'	2.98'	-3.63'	SEE NOTE		
208	24" W	1880435.060	1175628.960	63.35' LT	3.08'	8.72'	11.80'	SUE QUALITY LEVEL "A"		
209	36" G	1883749.960	1175552.500	50.22' LT	-5.24'	5.99'	0.75'	SUE QUALITY LEVEL "A"		
210	36" G	1883756.720	1175845.280	50.63' RT	-6.85'	8.42'	1,566'	SUE QUALITY LEVEL "A"		
211	36" W	1883739.550	1175839.290	44.18' RT	-5.25'	5.86'	0.606'	SUE QUALITY LEVEL "A"		
212	18" BT	1884480.420	1175521.840	61.14' LT	-7.58'	4,95'	-2.634'	SUE QUALITY LEVEL "A"		
213	18" BT	1884480.320	1175509.110	73.87' LT	-3.89'	4.91'	1.019'	SUE QUALITY LEVEL "A"		
214	20" BT	1884487.060	1175860.740	85.82' RT	-0.82'	3.19'	2.370'	SUE QUALITY LEVEL "A"		
215	(1)2" (3).25" SL	1879776.080	1175973.630	71.39' RT	2.91'	4.08'	6.995'	SUE QUALITY LEVEL "A"		
215A	SEE NOTE	1879798.750	1175970.990	69.36' RT	SEE NOTE	13.00'	7.040'	SEE NOTE		
	,									

## NOTES

- TH #168 Unable to see gas due to ground water.
- TH #169A Unable to see gas due to back fill continually caving in.
- TH #174 We were unable to determine size due to ground water in the hole.
- TH #175 Attempt was made to expose phone duct but were unsuccessful due to extreme heavy compacted clay, we were only able to reach 9.12'
  TH #179 Attempt was made to find electric duct. Went down 15.15' & 2.5' radius of Reference Point.
  TH #186 Unable to expose due to mud and ground water, felt top and sides.

- TH #187 Unable to expose due to wet sand collapsing in hole.
  TH #189 Offset is taken from N. bound Dan Ryan fence line.
- TH #190 Unable to expose due to soil collapsing in hole
- TH #192 Telephone was buried/trenched underneath a slab of concrete with rough edges; width was 48"
- TH #195 Unable to expose due to deep roots in hole
- TH #200 Felt both sides of gas line but unable to cover completely for picture, doing so would

leave a void in soil because of angle of ground level. Back fill kept falling from uphill.

- TH #204 Found the utilities for the street lights at about 2' deep. Offset pulled from CL of Dan Ryan on ramp.
- TH #207 Could not expose due to collapsing sand. Had a good feel with the air lance. Offset taken from C/L of exit ramp
- TH #215A TBE could not find electric crossing, vacumed down 13'.

ALL INFORMATION SHOWN WAS OBTAINED FROM A LOCATION SURVEY.

Illinois Department of Transportation

I-90 /94 (NB & SB of Dan Ryan Expressway)

Chicago-Cook County

Sec No: (2122-921 PT1) R, (2021-922 PTI,2)

Contract No. 62584, 62585, 62586, 62589, 62693, 62694, 62695

TBE Project No.: IL09500164, 167, 168, 170, 171, 179, 180, 182, 204, 205,

206, 211, 212, 219, 221, 225, 226, 227, 228, 230, 232, 238

R E V ISIO N S																			
DATE	BY	DESCRIPTION	DATE	BY	DESCRIPTION	DATE	BY	DESCRIPTION	DATE	BY	DESCRIPTION	DATE	BY	DESCRIPTION	DATE	BY	DESCRIPTION	TBE GROUP, INC.	VERIFIED
2/13/06 5	X																	SOUTHERN REGION: FL, GA, SC, NC NORTHERN REGION: IL, IN, MI, OH, MD, NJ, NY PA, VA, CANADA	UTILITY
100											and the same of th	. 1						WESTERN REGION: AZ, NV, NM, TX, CA, OR, UT, WA	LOCATIONS