CONTRACT NO. 62584, 62585, 62586, 62589, 62693, 62694, 62695 6

EXISTING GI	TOP OF UTILITY	OFFSET	EASTING	NORTHING	TYPE	SIZE &	TEST HOLE #
5.95'	-14.59'	40.98 RT	1178282.900	1839771.480	E		230
9.39'	-16.67'	7.63 LT	1178262.450	1839717.190	E	····	231
4.58'	-13.90'	54.90 RT	1177722.670	1847362.650	BT	24	232
6.00'	-15.30'	1.06 LT	1177666.640	1847364.070	BT		233
5.50'	-14,90'	4.50 LT	1177663.330	1847359.460	вт		233A
7.70'	-17.19'	5.81 RT	1177612.300	1847358.540	BT	24	234
4.98'	-14.25'	50.00 LT	1177556.570	1847354.940	BT	24	235
8.03'	-11.10'	56.67 RT	1177876.280	1842060.050	G	50	236
8.63'	-11.77'	59.39 RT	1177879.140	1842055.250	G	16	237
8.18'	-10.82'	0.43 RT	1177820.220	1842053.000	G	16	238
7.74'	-10.68'	5.02 LT	1177814.630	1842057.820	G	50	239
7.86'	-11.07'	58.61 LT	1177699.910	1842048.430	G	16	240
6.91'	-10.21'	58.90 LT	1177699.450	1842054.250	G	50	241
7.90'	-11.18'	62.02 RT	1177881.622	1842060,221	G	50	242
		·					
		The state of the s					
	-						
	and a management of a special of ground of the dispersion of the special of the s		- proposition with provide an action of the state of the				

VERIFIED UTILITY INFORMATION

VERIFIED UTILITY INFORMATION

416 of 916

TEST	SIZE & TYPE	NORTHING	EASTING	OFFSET	TOP OF	P OF EXISTING RE		COMMENTS				
HOLE #	DIES W TITE	110101111111	222221		UTILITY	CUT	GROUND ELEVATION	VOMMENT 10				
	H-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1		engelanden och senter									

-												
are en												
			, in the second				,					
							· · · · · · · · · · · · · · · · · · ·					
							· · · · · · · · · · · · · · · · · · ·					
		~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~										
			·									
	······································			·								
		***************************************										
					_	_		·				
				-								
							-13					
					:							
							***************************************					
				Action and the second								
L												

## NOTES

TH# 230 COULD NOT SEE DUCT DUE TO EXCESSIVE GROUND WATER BUT PROBED AND FELT SIDES AND TOP OF 48" WIDE DUCT. TH# 231 COULD NOT SEE DUCT DUE TO EXCESSIVE GROUND WATER BUT PROBED AND FELT SIDES AND TOP OF 24" WIDE DUCT.

TH# 233 & 233A WE WERE NOT ABLE TO EXCAVATE ANY DEEPER THAN DEPTHS RECORDED DUE TO EXTREMELY HARD SOIL CONDITIONS. WE HAD A DIFFICULT TIME PIN POINTING DUCT PACKAGE ELECTRONICALLY, THIS IS THE REASON WHY WE ATTEMPTED MULTIPLE HOLES IN THIS LOCATION.

TH# 234 & 235 NOT ABLE TO SEE PHONE DUCT DUE TO EXCESSIVE WATER AND SAND CAVING IN, BUT PROBED AND WERE ABLE TO FEEL BOTH SIDES AND TOP OF 24" WIDE DUCT.

TH# 238 & 240 NOT ABLE TO SEE GAS MAIN, BUT WAS ABLE TO TO PROBE AND FEEL SIDES AND TOP OF 16" MAIN.

TH# 239 NOT ABLE TO SEE GAS MAIN, BUT WAS ABLE TO TO PROBE AND FEEL SIDES AND TOP OF 50" MAIN.

I-90 /94 (NB & SB of Dan Ryan Expressway)

Chicago-Cook County

Sec No: (2122-921 PT1) R, (2021-922 PTI,2)

Illinois Department of Transportation

Contract No. 62584, 62585, 62586, 62589, 62593, 62693, 62694, 62695

TBE Project No.: IL09500164, 167, 168, 170, 171, 179, 180, 182, 204, 205, 206, 211, 212, 219, 221, 225, 226, 227, 228, 230, 232, 235, 237, 238, 248, 249

ALL INFORMATION SHOWN WAS OBTAINED FROM A

-												. 1			1		m v v , m
																·	
								REVIS	810 N S								·
DATE	BY	DESCRIPTION	DATE	BY	DESCRIPTION	DATE	BY	DESCRIPTION	DATE	BY	DESCRIPTION	DATE	BY	DESCRIPTION	DATE	BY	DESCRIPTION
4.1	I		1	1													



VERIFIED UTILITY LOCATIONS