




(Looking West)







<u> PIER 3 - ELEVATION</u>

PIER 3 - END VIEW







## ABUTMENT 1 - ELEVATION (Looking West)

TYLIN INTERNATIONAL

. = . = . .

*LEGEND* 

Formed Concrete Repair (Depth =< 5")

Epoxy Crack Sealing

Epoxy Crack Sec

BILL OF MATERIAL

ITEM	UNIT	TOTAL
Epoxy Crack Sealing	FOOT	51
Formed Concrete Repair (Depth =< 5")	SQ FT	42

## SOUTH RETAINING WALL BETWEEN ABUTMENT 1 AND 2 - ELEVATION

(Looking North)

		SHEET 8 OF 12
REVISIONS NAME DATE	ILLINOIS DEPARTMENT	OF TRANSPORTATION
	F.A.I. 94 (DAN R) SUBSTRUCTE FOR CHICAGE EXISTING PIER 3	JRE REPAIR O RAIL LINK
	S.N. 016-0145 SCALE: N.T.S.	DESIGNED BY: MAF, DJR DRAWN BY: MAF, DJR
	DATE: MARCH 1, 2006	CHECKED BY: MI