

#### STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION



# ELEVATION EAST ABUTMENT (WB)




#### ELEVATION WEST ABUTMENT (WB)

#### <u>LEGEND</u>




CHECKED: DCD

Spalled Concrete with Exposed Reinf.



# ELEVATION EAST ABUTMENT (EB)



# ELEVATION WEST ABUTMENT (EB)

# BILL OF MATERIAL

Item	Unit	EΒ	WB	
Structural Repair of Concrete (Depth = < 5")	Sq. Ft.	i	9	

<u>Notes:</u> Condition Survey performed 1/15/2010.

Plan quantities assume that areas of "exposed reinforcing" will be repaired.

Repair areas are estimated, the Engineer shall determine actual repair locations and record them on the As-Built plans.

	Johnson, Depp & Quisenberry  CONSULTING ENGINEERS  Springfield, Illinois					
DESIGNED:	JDQ		DRAWN:	SJS		

# <u>ABUTMENTS</u> STRUCTURE NO. 086-0023(EB) & 0024(WB)

HEET 6	F.A.I. RTE.	SECTION				COUNTY	TOTAL SHEETS	SHEET NO.	
	72	86-10(RS-3)				SCOTT	48	40	
		STA. 200+00.00				CONTRACT	NO. 7	72A16	
	FED. RO	AD DIST. NO	).	ILLINOIS	FED.	AID	PROJECT		