



LEGEND
 ——— EXISTING JOINT
 ——— JOINT TO BE REPAIRED

NOTES:
 1. EXACT LOCATIONS OF PCC SPALL REPAIR TO BE DETERMINED BY THE ENGINEER.

REVISIONS		
NUMBER	BY	DATE

0 1 2
 THIS BAR IS EQUAL TO 2'
 AT FULL SCALE (34X22).
 PLOT 1

**MIDAMERICA ST. LOUIS AIRPORT
 ST. CLAIR COUNTY, ILLINOIS**

RUNWAY AND TAXIWAY JOINT REPAIR

ONE MEMORIAL DRIVE, SUITE 500
 ST. LOUIS, MO 63102
 (314) 436-5500
CMT
 CRANFORD, MURPHY & TILLY, INC.
 CONSULTING ENGINEERS
 © Copyright CMT, Inc.
 PROFESSIONAL ENGINEERING - 184-000813

**IL PROJECT: BLV-3886
 AIP PROJ: 3-17-0146-XX**

FILE: 05-07_JOINT_REPAIR.dwg
 DESIGN BY: LEW
 DRAWN BY: ASA
 CHECKED BY: BWG
 APPROVED BY: BWG
 DATE: APRIL 17, 2009
 JOB No: 09098-01

**JOINT REPAIR
 PLAN 02**