# TRANSPORTATION BULLETIN

## Millinois Department of Transportation

## **ADDENDUM NO. 1**

Dated: June 9, 2009

For: Transportation Bulletin Letting Date: June 12, 2009 Volume 12 No. 19r4 Dated: May 8, 2009 Rev. June 3, 2009

Item No. 19A Taylorville Municipal Airport Taylorville, Illinois Christian County Ill. Proj. No. TAZ-3890 AIP No. 3-17-0100-B11

### TO ALL PLAN HOLDERS:

#### **REVISED: Schedule of Prices**

Add: Pay Item AR800481 "Remove & Replace Bit. Pavement, Runway".

Insert revised Schedule of Prices dated 06/08/2009.

## **REVISED:** Section III - Special Provisions

Page 10 - ITEM AR401650 - Bituminous Pavement Milling

Add the following to Section 1.1:

The remaining millings shall be retained by the airport and stored (stockpiled) by the contractor for the airport's use at the location noted on Sheet 3 (Proposed Safety Plan). The location is inside an existing airport gate and shall be no closer to the runway centerline than 400 feet. The area allotted for the stockpile is 150 ft-long by 50 ft-wide. The stockpile should be located no closer to the

adjacent ditch slope than 50 feet. The contractor may use the turf areas adjacent to the runway to access this area, however, any damage sustained to the area shall be repaired to its preconstruction condition at the expense of the Contractor. All seeding and mulching necessary for the restoration shall be in accordance with Items 901 and 908, respectively. The cost to provide the delivery of the millings to this location including all equipment, materials, fuel and labor, as well as any restoration necessary shall be included in the cost for this pay item.

Add the following to the end of the Special Provisions:

#### ITEM AR800481 - REMOVE & REPLACE BIT. PAVEMENT, RUNWAY

#### DESCRIPTION

Following the completion of the Construction Plans an additional area of pavement failure was observed and is proposed to be repaired as part of the Project. As a temporary measure, the immediate area of failure was excavated and backfilled with Portland Cement Concrete. The extent of the temporary repair measures approximately 24-inches x 24-inches, and extends approximately 30-inches in depth. This volume of concrete will require removal and the area repaired in accordance with the Construction Plans and this Special Provision.

#### MATERIALS

Bituminous Surface Course. The bituminous used for this Item shall be an approved IDOT mix, and must have acceptance by the Division of Aeronautics, Materials Section <u>prior</u> to being used for this Pay Item. Check Sheet No. 21 of the Recurring Special Provisions shall apply to this material.

Crushed Aggregate Base Course. The aggregate (209) used for this Item shall be from an approved IDOT source, and must have acceptance by the Division of Aeronautics, Materials Section <u>prior</u> to being used for this Pay Item.

Separation Fabric. The separation fabric used for this Item shall be IDOT approved, and must have acceptance by the Division of Aeronautics, Materials Section <u>prior</u> to being used for this Pay Item. Check Sheet No. 9 of the Recurring Special Provisions shall apply to this material.

#### **CONSTRUCTION METHODS**

The areas to be replaced shall be sawed full-depth. The existing bituminous pavement and aggregate base within the limits of the repair area shown in the Construction Plans (25-ft x 25-ft, approximate Sta. 277+90) shall be removed and the subgrade inspected for settlement, soft spots, or other geotechnical failures – and repaired as necessary using approved replacement fill material from off site.

Following recompaction of the subgrade, separation fabric conforming to Item AR156513 – Separation Fabric of the Supplemental and Recurring Special Provisions (SSRSP) shall be installed. Crushed aggregate conforming to Item 209 shall be utilized to form a new aggregate base course within the area of removal as necessary, and compacted to within 95% of the maximum dry density of the material, to a depth consistent with the surrounding pavement structures (see Typical Sections in Construction Plans). Once the trench is cleaned and the base aggregate is compacted and accepted by the Resident Engineer, an application of Bituminous Tack Material conforming to Item AR603 of the Supplemental Specifications shall be applied to the vertical face of the trench and aggregate base. Lifts of bituminous surface course material (401) shall be placed in lifts not to exceed 3-inches in depth, and compacted in accordance with Item 401003 of the Recurring Special Provisions. The final lift shall be flush with the adjacent existing bituminous pavement. The excavated material will be removed from the Airport site and disposed of at the Contractor's expense. All repairs shall be made <u>PRIOR</u> to the remaining milling of the runway surface.

#### METHOD OF MEASUREMENT

The quantity of removed and replaced bituminous pavement, runway to be paid for shall be the number of sq. yds., completed, accepted, and measured in place by the Resident Engineer. The quantity of fill, fabric, aggregate, bituminous surface course, and bituminous tack material used for this item shall be considered incidental to the item and no additional compensation will be allowed.

#### **BASIS OF PAYMENT**

This Item of work will be paid for at the contract unit bid price per sq. yd. to remove and replace bituminous pavement, runway, which price shall be full compensation for all sawing, removal, milling (if utilized), disposal of waste material, application of tack material, placement of the fill, aggregate, and bituminous material; for furnishing all materials, labor, equipment, and incidentals necessary to complete this Item of work.

Payment will be made under:

Item AR800481 Remove & Replace Bit. Pavement, Runway - per sq. yd.

#### **REVISED: Construction Plans**

Sheet 2 - Summary of Quantities and Index to Sheets

Added: Item AR800481 - Remove & Replace Bit. Pavement, Runway, per square yard.

Sheet 3 – Proposed Safety Plan

Description: See addition of stockpile area.

Sheet 4 – Proposed Pavement Preparation Plan Sta. 262+00 to Sta. 276+00

Description: See revision to notes pertaining to Item AR401650 - Bituminous Pavement Milling, per square yard.

Sheet 5 - Proposed Pavement Preparation Plan Sta. 276+00 to Sta. 290+00

Description: See added notes pertaining to new pay item, Item AR800481 – Remove & Replace Bit. Pavement.

M03 ECMR003 PAGE 1 /08/09 3315	<u> ILL PROJECT TA-Z -3890</u>	TOTAL PRICE	11 -					1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	+ 1 1 1 1 1 1 1 1 1 1 1 1 1		1 4 1 1 1 1 1 1 1 1 1 1 1 1 1				
N ECMS002 DTGEC RUN DATE - 06 RUN TIME - 19	FED PROJECT - 17 - 0100 - B11	UNIT PRICE DOLLARS CEN			 	+   		 	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	 	 	₹   		 	TOTAL
# ILLINOIS DEPARTMENT OF TRANSPORTATION SCHEDULE OF PRICES CONTRACT NUMBER - TA002	3	QUANTITY	1.000	1.000	1.000	3,998.000	5,000.000	36,295.000)	1,037.000	3,130.000	12,703.000	35,259.000	214.000	70.000	
	IT NAME	UNIT OF MEASURE	L.S.	L.S.	L.S.	s.Υ.	• • •		S.Υ.		GAL	S.F.		R S.Y.	
	NAME CODE DIST AIRPOR AN 021 06 TAYLORVILLE MUNIC	PAY ITEM DESCRIPTION	ENGINEER'S FIELD OFFICE	TRAFFIC MAINTENANCE	HAUL ROUTE	SHOULDER ADJUSTMENT	CLEAN & SEAL BITUMINOUS CRACKS	BITUMINOUS PAVEMENT MILLING	REMOVE & REPLACE BIT. PAVEMENT	POROUS FRICTION COURSE	BITUMINOUS TACK COAT	PAVEMENT MARKING-WATERBORNE	PAVEMENT MARKING-BLACK BORDER	REMOVE & REPLACE BIT. PAVEMENT,	
STATE JOB	COUNTY N CHRISTIA	ITEM NUMBER	510	R150530	50540	52480	01661	01650	01910	402610	3510	620520	620525	R800481	

NOTE: \*\*\* PLEASE TURN PAGE FOR IMPORTANT NOTES \*\*\* \_\_^

ECMS002 DTGECM03 ECMR003 PAGE RUN DATE - 06/08/09 RUN TIME - 193315		THERE IS A DISCREPANCY BETWEEN
ILLINOIS DEPARTMENT OF TRANSPORTATION SCHEDULE OF PRICES CONTRACT NUMBER - TA002	HAVE A UNIT PRICE AND A TOTAL PRICE.	GOVERN IF NO TOTAL PRICE IS SHOWN OR IF THERE IS A DISCREPANCY BETWEEN UNIT PRICE MULTIPLIED BY THE QUANTITY.
TAYLORVILLE MUNICIPAL CHRISTIAN	NOTE: 1. EACH PAY ITEM SHOULD HAVE A UN	2. THE UNIT PRICE SHALL THE PRODUCT OF THE

- 3. IF A UNIT PRICE IS OMITTED, THE TOTAL PRICE WILL BE DIVIDED BY THE QUANTITY IN ORDER TO ESTABLISH A UNIT PRICE.
- 4. A BID MAY BE DECLARED UNACCEPTABLE IF NEITHER A UNIT PRICE NOR A TOTAL PRICE IS SHOWN.

. -