



	MAIN SPAN FLOORSYSTEM REPAIR SCHEDULE							
ID. NO.	Item	Location	Action					
24	Stringers	PP2-PP6, PP6'-PP2'	Strengthen					
25	Floorbeams	FB 14, FB 17, FB 20, FB 22, FB 25, FB 25', FB 22', FB 20', FB 17', FB 14', FB 8', FB 0'	Strengthen and/or retrofit for cracking					
26	Floorbeam	FB 23, North End	Remove delamination on bottom flange					
27	Floorbeams	FB IS, FB 3S, FB 8 at S7, FB 9S, FB 10S, FB 11S, FB 16N and S, FB 19N, FB 21N and S, FB 24N, FB 23'N 4' from end, FB 23'S, FB 21'N 4' from end, FB 11' between S1-S2 and S6-S7, FB 9'N 4' from end, FB 6'N 4' from end, FB 4' at S7	Repair floorbeam webs					
28	Bottom Lateral Connection Plates	LOS-LIN at LOS, LIN-L2S at LIN, L2N-L3S at L2N, L3N-L4S at L3N, L4N-L5S at L5S, L5N-L6S at L6S, L6N-L7S at L7S, L10S-L11N at L10S, L12N-L13S at L13S, L15N-L16S at L16S, L17N-L18S at L18S, L18N-L19S at L19S, L22'N-L21'S at L21'S, L20'N at L21'S, L20'N-L19'S at L19'S, L18'N-L17'S at L18'N, L16'N-L15'S at L16'N, L13'S-L12'N at L12'N, L7'N-L6'S at L6'S, L6'N-L5'S at L6'N	Replace bottom lateral connection plates or end stay plates					

Not

For 2013 NBIS defect item number and sheet reference, see sheets S4 and S5.

MODJESKI and MASTERS Experience great bridges.

USER NAME =	DESIGNED - MEL	REVISED
	CHECKED - CDB	REVISED
PLOT SCALE =	DRAWN - AEC	REVISED
PLOT DATE = 05/02/2014	CHECKED - JMH	REVISED

STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION

GENERAL PLAN	AND	ELE\	/ATI	ION	-	MAIN	SPAN	REPAIRS	3
S.N. 082–600	1 MI	K B	RID	ЗΕ	OVE	R MIS	SISSIPF	PI RIVER	
	CHEE	T NO	ca	ΛE	C130	CHEETS			

F.A.P. RTE.	SECTION			COUNTY	TOTAL SHEETS	SHEE NO.
799	1BR, DRS	-2		ST. CLAIR	156	27
				CONTRACT	NO. 7	6B03
	11.1.1	NOTE FED	A ID	DDO IECT		