


OUTSIDE PLATE AT PANEL POINT U8N AND U8S (U8'N AND U8'S SIMILAR) (Span 9 and 11)

INSIDE PLATE AT PANEL POINT U8N AND U8S (U8'N AND U8'S SIMILAR) (Span 9 and 11)

GUSSET PLATE STRENGTHENING



<u>REPAIR P. U8A</u> P. 34" x 734" x 1'-7'2"

Field drill holes using existing holes as template. Remainder of holes may be shop or field drilled.

Procedure: Install repair plates one at a time.

BILL OF MATERIAL

Item	Unit	Total
Structural Steel Repair	Pound	360

All bolted connections shown on this sheet shall be made with 1" dia. H.S. bolts unless otherwise noted.



USER NAME =	DESIGNED - MEL	REVISED
	CHECKED - CDB	REVISED
PLOT SCALE =	DRAWN - PRC	REVISED
PLOT DATE = 05/02/2014	CHECKED - MEL	REVISED

STATE OF ILLINOIS **DEPARTMENT OF TRANSPORTATION**

		TE STRENGTHENING – OVER MISSISSIPPI RIV	
S	SHEET NO. S57 OF	S138 SHEETS	

F.A.P. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
799	1BR, DRS-2	ST. CLAIR	156	75
		CONTRACT	NO. 7	6B03
	THE THOUGHT CO. AT	ID DDO IECT		