

INFRARED THERMOGRAPHIC INSPECTION RESULTS

FIELD OBSERVATIONS SUMMARY		TOPS	IDE	LEGEND		
ITEM	UNIT	QUANT.	%	DELAMINATION		
TOTAL AREA	f+2	7633		SPALI		
SHADE/DEBRIS	f †2 f †2	0		DEBOND		
DELAMINATION		246	3.2			
SPALL	Ft2	0	0	ASPHALT PATCH		
DEBOND	f†²	590	7.7	SUBSURFACE PATCH		
ASPHALT PATCH	f+²	0	0	SHADE/DEBRIS	TITTO	
SUBSURFACE PATCH	f+2	0	0	SHADE/ DEDING	alle	



ANTICIPATED DECK REPAIR QUANTITIES (ft.2)

SPAN	2000 SURV RESULTS		2005 ANTICIPATED PARTIAL DEPTH REPAIRS					
SII	410				520			
SI2	530				670			
SI3	250				320			
OLIANTIT	IES IN THIS	TABLE	ARE	FOR	INFORMATIONAL			

QUANTITIES IN THIS TABLE ARE FOR INFORMATIONAL PURPOSES ONLY AND ARE INCLUDED UNDER THE BRIDGE DECK HYDRO-SCARFICATION AND BRIDGE DECK MICROSILICA CONCRETE OVERLAY PAY ITEMS, REFER TO SPECIAL PROVISIONS.

NOTES:

WISS, JANNEY, ELSTNER ASSOCIATES, INC. CORE LOCATIONS DESIGNATED AS "WJE". EARTH TECH, INC. CORE LOCATIONS DESIGNATED AS "ET".

AREAS OF DECK DELAMINATIONS AND SPALLS SHOWN REQUIRING REPAIR ARE ESTIMATED. ACTUAL REPAIR LOCATIONS SHOULD BE SHOWN ON AS-BUILT DRAWINGS.

TOTAL

SHEET S-27 OF S-44

94

INFRARED INSPECTION DATE: 7/24/00-7/26/00 SURFACE TYPE: ASPHALT OVERLAY

INFRARED THERMOGRAPHIC INSPECTION RESULTS

								1/1/	MAMED	I TERMOGRAPHIC INSPECTION RESULTS
		R 1				T E C		REVISIONS		STATE OF ILLINOIS
E	A I		т	Н	7		H	NAME	DATE	DEPARTMENT OF TRANSPORTATION REHABILITATION AND RETROFIT REPAIRS
L	^ I	¥.	•	11			10.0			FAI ROUTE 70
										POPLAR STREET BRIDGE APPROACHES
									l	ST. CLAIR COUNTY
INSPEC	TED: TC					CADD:	MAZMD DSZEG	and the state of t		STRUCTURE NO. 082-0142 (RAMP S)
ANALYS	SIS: TC					CHECKED:	ĐU			SCALE:
										DATE: 02/28/2006

TENAMA
CHECKED CSD

DRAWN CLK
CHECKED JPD