

003-029	м					
	11		соок		344	201
		ro s	TA.			
IST. NO.	ILLIN	OIS F	ED.	AID	PROJECT	
	DIST. NO.	IST. NO. ILLIN	IST. NO. ILLINOIS		NIST. NO. ILLINOIS FED. AID	IST. NO. ILLINOIS FED. AID PROJECT

Notes:

Existing longitudinal reinforcement in slab and barriers shall be cleaned, straightened and incorporated into new construction.

Bend #4 vertical parapet bars in field to clear the top flange of fascia girders as needed.

Remove existing rails, posts, anchors or other attachments as required for the partial removal of barriers for the joint reconstruction. Reinstall removed components as required to restore original condition. Cost included with "Concrete Removal" and "Concrete Superstructure".

Place bars in parapet to maintain $1_2''$ cl.

Care should be exercised during concrete removal not to damage existing shear studs.

Top of Parapet

50

BILL OF MATERIAL

Item	Unit	Total 🛆
Deck Silicone Joint Sealer, 1"	Foot	(117)
Silicone Joint Sealer, 1"	Foot	10,486

^	REVISIONS NAME DATE		ILLINOIS DEPARTMENT	OF TRANSPORTATION	
1	ADDENDUM NO. 1	6/29/06	F.A.I. 94/90 (DAN R	YAN EXPRESSWAY)	Мd
			SB DAN RYAN ELE	EVATED BRIDGE	3145
			REPAIR FROM 15TH	TO 28TH STREETS	4
			TYPICAL DECK SLAB AND SILICONE JOINT		5
					2006
			SCALE: NTS DATE: 5/25/2006	DRAWN BY: BDC CHECKED BY: BLU	/67/
	I	1	5H1C1372372000	CHECKED DI. DEU	Q,