



PLAN

Hatched areas indicate Deck Slab Repair (Partial) Areas of deck repair are estimated. Actual locations shall be shown by the Engineer for As Built Plans.




TYPICAL END OF SEAL TREATMENT



of the parapet.

SECTION THRU JOINT



TYPICAL DECK REPAIR DETAIL

Cross hatched areas indicate Deck Slab Repair (Full Depth, Type II)

BILL OF MATERIAL

	-	
Item	Unit	Quantity
Deck Slab Repair (Partial)	Sq. Yd.	100
Deck Slab Repair (Full Depth, Type I)	Sq. Yd.	132
Protective Shield	Sq. Yd.	240
Polymerized Hot-Mix Asphalt Surface Course, Mix ''D'', N90	Ton	62
Silicone Joint Sealer, 2"	Foot	107
Polymer Concrete	Cu. Ft.	10.4
Polymerized Leveling Binder (Machine Method), N5O	Ton	26

DESIGNED VHV CHECKED DAB	EXAMINED	Jugne 1. John	DATE	JUNE 29, 2011
DRAWN Kyle M. Steffen	PASSED	ACTING ENGLISHED OF STRUCTURAL HERVICES	REVISED	
CHECKED VHV DAB		ACTING ENGINEER OF BRIDGES AND STRUCTURES	REVISED	

STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION

-	DECK	PATCH	ING	DETAILS	·····
	SN	081-	0017	(NB)	
_	SHEET	F NO. 3	OF 3	SHEETS	