

BENCHMARK DESCRIPTIONS

<u>4818-1</u>

STA. 1051+02 O/S = 0.15' RT Description: Brass Stem Location: To reach from the intersection of I-74 and Kickapoo Creek, go east on I-74 for 1300' to mark on the left. Said mark is a broken brass stem on the west side of a concrete drop box. Drop box is located 50' east of a turn around.

<u>4818-2</u>

STA. 1040+05.7 O/S = 69.1' LT Description: Chiseled Square Location: Said mark is a chiseled square located on the top of the NE wingwall of the North structure over Kickapoo Creek on I-74.

<u>4818-3</u>

STA. 1037+98 O/S = 28.8' RT Description: Chiseled Square Location: Said mark is a chiseled square located on the top of the NW wingwall of the South structue over Kickapoo Creek on I-74.

<u>4814-4</u>

0.041E = 8/2/2007 NAME = ct/projecta/d505 SCALE = 21.1765 '/ JN, I NAME = collerbu

PLOT FLLE PLOT USER STA. 1021+11.4 O/S = 10.8' LT Description: Chiseled Square Location: To reach from the intersection of I-74 and Kickapoo Creek, go west on I-74 for 1500' to mark on the left. Said mark is a chiseled square located on the SE comer of a drop box on the north side of the median.

					CONTRACT	NO. 70	671
1.1.00.01		F.A.L RTE.	SECTION		COUNTY	TOTAL	SHEE NO.
<u>) + 00.81</u>		74	(57~22)BR	2-2	MCLEAN	42	8
		STA.			O STA.		
		FED. ROA	D DIST. NO.	ILLING	IS FED. AID	PROJECT	
	WESTBOUND 174						N A
	CORNER OF UDERDRAIN 11.0' 35 ⁸⁵ 12.15 S.E. CO	MAG N IN E.O	<u>AII.</u> 				A
	12.15 S.E. CO		AIL S.			· · · · · · · · · · · · · · · · · · ·	A
UA	12.15 S.E. CO	RNER OF	A <u>IL</u>			· · · · · · · · · · · · · · · · · · ·	A
	12.15 S.E. CO	RNER OF	<u>Ail</u>				A
UA	12.15 S.E. CO	RNER OF	AIL 3.				A
UA	12.15 S.E. CO UNDE	RNER OF	Ail. S				A
UA	12.15 S.E. CO UNDE	RNER OF	Ail. S				A