

NORTH ABUTMENT ELEVATION (Looking North)

\* Additional Concrete Repair may be required at brace connection locations as directed by the Engineer. Cost included with Removal of Existing Superstructures Superstructures.

Goombe-Bloxdorf P.C. -CIVIL ENGINEERS- -STRUCTURAL ENGINEERS- -LAND SURVEYORS- -LAND SURVEYORS- -CIVIL ENGINEERS- -LAND SURVEYORS- -CIVIL ENGINEERS- -LAND SURVEYORS- -CIVIL ENGINEERS- -LAND SURVEYORS- -CIVIL ENGINEERS- -CIVIL ENG		
-CIVIL ENGINEERS- -STRUCTURAL ENGINEERS- LAND SUBVEYORS CME 10 SHEETS		Coombe-Bloxdorf P.C.
LAND SUBVEYOPS DRAWN BY CME 10 SHEETS	4/27/10 2936	
	DRAWN BY UME 10 SHEETS	
Design Firm License No. 184-002703 CME/MCB FED. F		Design Firm License No. 184-002703

## LEGEND

Denotes Structural Repair of Concrete (Depth Less Than or Equal to 5'')

## BILL OF MATERIAL TWO ABUTMENTS

ITEM	UNIT	TOTAL
Structural Repair of Concrete (Depth Equal to or Less Than 5 In.)	Sq. Ft.	1

## ABUTMENT REPAIR DETAILS STRUCTURE NO. 077-0035

	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
	16BR-1	PULASKI	68	54
		CONTRACT	NO. 78	071
C	DAD DIST. NO. ILLINOIS FED. A	ID PROJECT		