



EAST FACE




WEST FACE

PIER 1



EAST FACE



WEST FACE

PIER 2

BILL OF MATERIAL

ITEM	UNIT	QUANTITY
Epoxy Crack Injection	Foot	16.0

DESIGNED - FESSEHA TEKLEHAIMANOT	EXAMINED - <i>Jaime F. Schaff</i> ACTING ENGINEER OF BRIDGE DESIGN	DATE - SEPTEMBER 16, 2014
CHECKED - JOSUE ORTIZ-VARELA	PASSED - <i>Carl Kasper</i> ACTING ENGINEER OF BRIDGES AND STRUCTURES	REVISED
DRAWN - MICHAEL B. MOSSMAN		REVISED
CHECKED - F.T. / J.O.V. / G.R.A.		

**STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION**

**SUBSTRUCTURE REPAIRS
STRUCTURE NO. 018 - 0041 (WB)**

SHEET NO. 28 OF 36 SHEETS

F.A.I. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
70	(18-45HB-1)BR	CUMBERLAND	43	35
CONTRACT NO. 74187			ILLINOIS FED. AID PROJECT	