



**ELEVATION**  
(Showing Inside Face of East Wall)

*Note:*  
The limits of Epoxy Crack Injection shown are approximate. The limits of Epoxy Crack Injection may vary in the field. Changes in the quantity of Epoxy Crack Injection shall be approved by the Engineer.

~~~~~ Indicates Epoxy Crack Injection Required

FILE NAME = I74+73.19-76789-004.dgn



USER NAME = jdinkelmann  
 Illinois Design Firm Number 184,001670  
 PLOT SCALE =  
 PLOT DATE = 8/8/2014

DESIGNED - JD  
 CHECKED - BB  
 DRAWN - WS  
 CHECKED - CJF

REVISED -  
 REVISED -  
 REVISED -  
 REVISED -

STATE OF ILLINOIS  
 DEPARTMENT OF TRANSPORTATION

EXISTING BOX CULVERT REPAIR DETAILS  
 STRUCTURE NUMBER 042-2470

SHEET NO. 4 OF 4 SHEETS

| F.A.S. RTE.               | SECTION   | COUNTY | TOTAL SHEETS | SHEET NO.          |
|---------------------------|-----------|--------|--------------|--------------------|
| 752                       | 101-2RS-1 | JERSEY | 438          | 210                |
|                           |           |        |              | CONTRACT NO. 76789 |
| ILLINOIS FED. AID PROJECT |           |        |              |                    |