
2'-0"

ELEVATION - SOUTH ABUTMENT
S.N. 101-0031

STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION



EAST WALL SOUTH ABUTMENT
S.N. 101-0032

I'-0" I'-0" * (5VB, 5HB,			ROUTE NO.	SECTION
10-16				*
10-16	_	.6"	FED. ROAD DIST.	NO. 7
		3.0.	* (5VB,	5HB,

WEST WALL NORTH ABUTMENT
S.N. 101-0032




SB

CHECKED

Formed Concrete Repair (Depth equal to or less than 5")

Epoxy Crack Sealing



BILL OF MATERIAL

		ITEM	UNIT	TOTA
DESIGNED	SB, DP	Formed Concrete Repair (Depth Equal to or Less Than 5")	Sq. Ft.	15
CHECKED	SB	Epoxy Crack Sealing	Foot	15
DRAWN	BH, BS			
	-			

TYP. SECTION THRU EXIST. PARAPET

SHOWING STEEL RETROFIT RAIL
(For Information Only)

Note: Contractor must ensure that rails are properly marked before removal to ensure proper placement during re-erection.

ABUTMENT REPAIRS
F.A.P. Route 303 & F.A.P. Route 738
(IL 251) OVER Rockton Road
SECTION (5VB, 5HB, 1-2HB)M
WINNEBAGO COUNTY
SN 101-0031 & 101-0032

SHEET NO. 6

9 SHEETS

23

CONTRACT #64A88

-Winnebago

1-2HB)M

36