

### STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION





TOTAL SHEETS St. Clair 7 5 ILLINOIS FED. AID PROJECT

Contract: 76906









### SECTION B-B

DESIGNED A.T.H.	May 5, 2005
CHECKED J.S.B.	EXAMINED John a. Morris
DRAWN <b>Drew Christopher</b>	PASSED SERVICES PASSED SERVICES SALPH E. CILIBERSON ENGINEER OF BRIDGES AND STRUCTURES
CHECKED A.T.H. J.S.B.	embineer of Buildes ANU STRUCTURES


REP-1 1-14-2005

...\prajects\mac00034\0820150.dgn 5/5/2005 30:25:50 AM

# Oak timber blocks Place an HP Beam or a 6" I-Beam (Min.) $\pm 1'$ -6" in length on bottom flange. Beam shall have 38" stiffeners (3 each side of beam) welded in place. Bent bottom flange shall be straightened before starting any horizontal straightening operation. -Shim Æ's as req'd. `\_Timber wedae .3⊿" Bra. P 50 Ton (min.) jack -Timber block-


### SUGGESTED VERTICAL STRAIGHTENING DETAIL

(To correct flange rotation.)



## GRINDING DETAIL

Grind existing nicks, gouges and shallow cracks in the damaged beams as detailed. Ground surfaces shall be inspected for cracks using magnetic particle testing prior to initiating any beam straightening operations. Any cracks that cannot be removed by grinding approximately  $l_4$ " deep shall be identified and reported to the Bureau of Bridges and Structures for further disposition. Ground surfaces shall be spot cleaned and painted with an aluminum epoxy mastic primer followed by a finish coat to match the color of the existing beam. Cost of grinding, testing and spot painting included with Beam Straightening.



### SUGGESTED VERTICAL STRAIGHTENING DETAIL

(To correct localized vertical flange deformations.)

\* Edge of plate shall line up with edge of deformation.

#### Note:

Braces and jack assembly shall be placed on same side of web. Bent bottom flange shall be straightened before starting any horizontal straightening operations.



### EXISTING DEFORMATION TO BE STRAIGHTENED

(Looking North) (Approximate max. deflections) Deflected length of beam to be straightened is approximately 8'-0".

> BEAM STRAIGHTENING F.A.I. RT 64 ST. CLAIR COUNTY SN 082-0150