

NOTE:
VEGETATION MUST BE REMOVED AT ALL PROPOSED PAVEMENT AREAS, COST INCIDENTAL TO ITEM AR152410.

TYPICAL SECTION - TAXILANE 10

STA 11+16.10 TO 15+21.10
(SECTION SHOWN LOOKING SOUTHEAST)
*SEE PLANS AND CROSS SECTIONS FOR STA 10+00 TO 11+16.10



TYPICAL SECTION - TAXILANE 50

(SECTION SHOWN LOOKING SOUTHEAST)



NOTE: PAVEMENT MILLING TO BE AS NECESSARY TO PROVIDE A MINIMUM 1.5" PAVEMENT THICKNESS.

SECTION - SOUTHEAST ACCESS TAXIWAY AT TAXILANE 50 ℄

(SECTION SHOWN LOOKING EAST)



NOTES

1. REMOVED BITUMINOUS PAVEMENT AND AGGREGATE BASE TO BE DISPOSED OF AT AN OFFSITE LOCATION, COST INCIDENTAL TO REMOVE AND REPLACE BITUMINOUS PAVEMENT.
2. ALL ITEMS ASSOCIATED WITH THE BITUMINOUS PAVEMENT REMOVAL AND REPLACEMENT TO BE INCLUDED IN ITEM AR401916 EXCEPT FOR BITUMINOUS PAVEMENT SAWING WHICH IS TO BE PAID AS ITEM AR401665 AND BITUMINOUS/BITUMINOUS SEAL PAID AS ITEM AR401660.

BITUMINOUS PAVEMENT REMOVAL AND REPLACEMENT - TYPE B



NOTES

1. REMOVED P.C.C. PAVEMENT AND AGGREGATE BASE TO BE DISPOSED OF AT AN OFFSITE LOCATION, COST INCIDENTAL TO REMOVE AND REPLACE P.C.C PAVEMENT-6".
2. ALL ITEMS ASSOCIATED WITH THE P.C.C. PAVEMENT REMOVAL AND REPLACEMENT TO BE INCLUDED IN ITEM AR501910 EXCEPT FOR P.C.C. PAVEMENT SAWING WHICH IS TO BE PAID AS ITEM AR501665.
3. P.C.C. PAVEMENT JOINTS TO MATCH EXISTING.

REMOVE AND REPLACE P.C.C. PAVEMENT - 6" DETAIL



NOTE:
P.C.C. JOINT SEALING FOR PAVEMENT PATCH IS INCIDENTAL TO ITEM AR501910.

P.C.C./P.C.C. SEAL



BITUMINOUS TAPER DETAIL



NOTE BITUMINOUS JOINT SEALING TO BE PAID UNDER ITEM AR401660

BITUMINOUS/BITUMINOUS SEAL

LEGEND

1. EXISTING BITUMINOUS PAVEMENT
2. EXISTING BITUMINOUS AGGREGATE BASE COURSE
3. REMOVE AND REPLACE BITUMINOUS PAVEMENT- TYPE B, ITEM AR401916
4. BITUMINOUS PAVEMENT MILLING, ITEM AR401650
5. PROPOSED SUBGRADE PREPARATION:

   CUT AREAS - REMOVE TOPSOIL, ADDITIONAL CUT AS NECESSARY TO FINISHED SUBGRADE ELEVATION. ADDITIONAL UNDERCUT IN AREAS AS DETERMINED BY ROLL TEST.

   FILL AREAS - REMOVE TOPSOIL, ADDITIONAL UNDERCUT IN AREAS AS DETERMINED BY ROLL TEST.
6. PROPOSED BITUMINOUS SURFACE - 2", ITEM AR401610
7. PROPOSED BITUMINOUS BASE COURSE - 2", ITEM AR201610
8. PROPOSED BITUMINOUS PRIME COAT, ITEM AR602510
9. PROPOSED BITUMINOUS TACK COAT, ITEM AR603510
10. PROPOSED CRUSHED AGGREGATE BASE COURSE - 10", ITEM AR209510
11. POROUS BACKFILL NO. 2, ITEM AR705412
12. PROPOSED 4" PERFORATED UNDERDRAIN, ITEM AR705504
13. PROPOSED 4" TOPSOIL, ITEMS AR905510 AND AR905520
14. PROPOSED STORM SEWER, SEE PLAN AND SCHEDULE
15. PROPOSED GRANULAR DRAINAGE SUBBASE-4", ITEM AR800927
16. PROPOSED SEPARATION FABRIC, ITEM AR156513
17. REMOVE AND REPLACE P.C.C. PAVEMENT - 6", ITEM AR501910

WA055

HANSON

HANSON PROFESSIONAL SERVICES INC.

815 Commerce Drive, Suite 200
Oak Brook, Illinois 60523
Telephone: 630.990.3800
Fax: 630.990.3801

Waukegan Regional Airport
Waukegan Regional Port District

3580 North McAree Road
Waukegan, Illinois 60087
Phone: 847.244.0055
Fax: 847.244.3813

WAUKEGAN REGIONAL AIRPORT

CONSTRUCT NEW T-HANGAR APRONS, TAXIWAYS AND AUTO ACCESS

IDA PROJECT NO. UGN-3499

No.	Drawing Issue Description	Date	By

Date

JANUARY 27, 2006

Sheet Title

TYPICAL SECTIONS
NEW HANGAR PAVEMENTS

831-04TXYD	Project Number
AAP	11/15/05 Layout By Date
AAP	11/15/05 Designed By Date
KLK/RMH	01/23/06 Reviewed By Date
KLK	AAP Drawn By

Sheet No. 6

AAP
01/23/2006, 11:16 AM
I:\04Jobs\00831\83104TXYD_REVICIVIL\Sheet\08 Typical Sections.dgn