


Silicone Joint Sealer, 1.75"-Existing Steel P -Backer rod having a diameter Existing ½" x ½"— Bar to remain, 25% greater than joint opening Back of at the time of installation.

(Typ.)

Abutment

-1³₄''at 50°F (at rt. L's)



SECTION B-B Curb Repair SRC ≤ 5"

BILL OF MATERIAL

ITEM	UNIT	TOTAL
Deck Slab Repair (Partial)	Sq.Yd.	175
Structural Repair Of Concrete (Depth Equal To Or Less Than 5 inches)	Sq.Ft.	78
Structural Repair Of Concrete (Depth Greater Than 5 inches)	Sq.Ft.	27
Approach Slab Repair (Partial Depth)	Sq.Yd.	5.3
Plug Existing Deck Drains	Each	12
Silicone Joint Sealer, 1.75"	Foot	88

** Work shall be performed in accordance with Special Provision Deck Slab Repair (Special)

NOTES:

- 1. Remove the existing preformed joint seals and replace with silicone joint sealer as detailed in Section A-A.
- 2. Areas of proposed deck repairs are estimated. Actual type, location and dimensions of deck repairs are to be determined by the Engineer during construction.
- 3. Removal of Silicone and Neoprene joint shall be included in the cost of Silicone Joint Sealer, 1.75".
- Contractor may remove and replace guardrail components to facilitate joint replacement work. Cost included with Silicone Joint Sealer, 1.75".

USER NAME =	DESIGNED - GMK	REVISED -	
PLOT SCALE =	DRAWN - GFP	REVISED ~	DB STERLIN CONSULTANTS, INC. 123 N. WACKER DRIVE SUITE 2000
PLOT DATE =	CHECKED - WPK/GMK	REVISED -	CHICAGO, ILLINOIS 60606 TEL. (312)857-1008 FAX (312)857-1056
FILE NAME =	DATE - 01/21/2011	REVISED -	

SECTION A-A

CTATE	. OF	ILLINOIS
SIAIE	: Ur	ILLINUIS
DEDADTMERIT	UE .	TRANSPORTATION
DELWUIMEIM:	UF	INAIVOPUNIAIIUW

	I80	OVE	RA	EPAIR OCK 1 099-0	RUN	N CREEK	
SHEET	NO. S-	2 OF	S-6	SHEETS	5		

	F.A.I. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
	80	99-1-RS-4	WILL	116	90
4			CONTRACT	NO. 6	0м63
	FED. F	OAD DIST, NO. 1 ILLINOIS FED. AI	D PROJECT		