

## UNDERSIDE DECK SURVEY

## BILL OF MATERIAL

ITEM	UNIT	TOTAL
Cleaning and Painting Exposed Rebar	Sq.Ft.	1580

## LEGEND



Remove all loose concrete, blast clean rebars and re-epoxy coat rebars

## NOTE

Areas of proposed deck repairs are estimated. Actual type, location and dimensions of deck repairs are to be determined by the Engineer during construction.

USER NAME =	DESIGNED	- GMK	REVISED -	
PLOT SCALE =	DRAWN	- GFP	REVISED -	DB STERLIN CONSULTANTS, INC. 123 N. WACKER DRIVE BUITE 2000
PLOT DATE =	CHECKED	- WPK/GMK	REVISED -	CHICAGO, ILLINOIS 60808 TEL. (312)857-1008 FAX. (312)857-1056
FILE NAME =	DATE	- 01/21/2011	REVISED -	

STATE	OF	ILLINOIS
DEPARTMENT	0F	TRANSPORTATION

		OVER		AIR PLAN RUN CREE 146	K
 SHEET	NO. S-	3 OF S-	6 SHEETS		

A.I.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
30	99-1-RS-4	WILL	116	91
		CONTRACT	NO. 6	0м63
n o	OAD DICT NO 1 THE THORE FED A	TO DOO ITOT		