

SIGNING FOR FLAGGING OPERATIONS AT WORK ZONE OPENINGS

WORK ZONE EXIT OPENING





NOTES:

- 1. THE ARROWBOARD, THE FLAGGER AHEAD SIGN AND THE TRUCKS LEAVING HIGHWAY SIGN SHALL BE REMOVED OR TURNED AWAY FROM TRAFFIC AND THE EXIT AND ENTRY OPENINGS SHALL BE CLOSED WHEN THE FLAGGING OPERATION CEASES. NON OPERATING EQUIPMENT SHALL COMPLY WITH ARTICLE 701.11
- 2. WORK ZONE EXIT OPENINGS SHOULD BE A MINIMUM OF ONE HALF MILE APART.
- 3. EXITING THE WORK ZONE AT ANY PLACE OTHER THAN AT A WORK ZONE EXIT OPENING WILL BE PROHIBITED.
- 4. ALL VEHICLES SHALL ENTER THE WORK ZONE AT ENTRY OPENINGS, USING THEIR TURN SIGNALS TO WARN MOTORISTS

ALL DIMENSIONS ARE IN INCHES (MILLIMETERS)
UNLESS OTHERWISE SHOWN

FILE NAME =	USER NAME = leyso	DESIGNED -	REVISED -	J.A.F. 04-03			SIGNING FOR FLAGGING OPERATIONS		F.A	SECTION	COUNTY	TOTAL SHEET
v:\diststd\22x34\to18.dgn		DRAWN -	REVISED -	J.A.F. 02-06	STATE OF ILLINOIS				IXIL.			388 256
	PLOT SCALE = 50.000 '/ IN.	CHECKED -	REVISED -	S.P.B. 01-07	DEPARTMENT OF TRANSPORTATION	AT WORK ZONE OPENINGS SCALE: NONE SHEET NO. 1 OF 1 SHEETS STA. TO STA.				TC-18	CONTRACT NO. AID PROJECT	
	PLOT DATE = 1/26/2010	DATE -	REVISED -	S.P.B. 12-09					FED. RO			