





TILE REPAIR AT STRUCTURE 057-8009
STA. 270+82




TILE REPAIR AT STRUCTURE 057-8015
STA. 339+63



NOTES:

- THE INSPECTION WELL LID FOR P.C.C. PIPE SHALL BE CONSTRUCTED OF 3/8" (10 mm) CAST IRON AND PROVIDED WITH A 1" (25 mm) DIAMETER HOLE IN CENTER. THE LID FOR THE OTHER PIPE MATERIALS SHALL BE A GRATE ASSEMBLY PREFABRICATED FOR AND COMPATIBLE WITH THE PIPE SYSTEM.
- FOR ADDITIONAL INFORMATION SEE DISTRICT DETAIL NO. 61101011A ON SHEET #59

CONCRETE PIPE STANDARD SIZES	
STORM SEWER	RISER
6" (150)	6" (150)
8" (200)	6" (150)
10" (250)	8" (200)
12" (300)	10" (250)
OR GREATER	



FILE NAME =	USER NAME = oglebj	DESIGNED -	REVISED - 11/06
ci:\pwork\pwork\ogled\0244982\0570783-sht-Tile Details.dgn		DRAWN -	REVISED -
	PLOT SCALE = 40.0000' / in.	CHECKED -	REVISED -
	PLOT DATE = 10/10/2012	DATE -	REVISED -

STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION

FIELD TILE REPAIR DETAILS

SCALE: _____ SHEET NO. ____ OF ____ SHEETS STA. _____ TO STA. _____

F.A.P. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
315	119RS-4, 18RS & (57-10)RS	MCLEAN	222	58
CONTRACT NO. 10783				
FED. ROAD DIST. NO. - [ILLINOIS] FED. AID PROJECT				