

ROUTE NO. TOTAL SHEET SHEET NO. 13 COUNT FAP 840 * 25 IROQUOIS 39 14 SHEETS FED. RDAD DIST. NO. ILLINOIS FED. AID PROJE 66647 123-BR-1 -Burn existing dowel rods flush with existing pier surface. Grind existing dowel rods smooth and seal with epoxy. Cost is included with Removal of Existing Superstructure (Typ.) -Fabric Bearing Pad 1-9"x¹2"x2'-9" typical except as noted PIER DETAILS IL 49 OVER PIGEON CREEK

> FAP ROUTE 840 - SECTION 123-BR-1 IROQUOIS COUNTY STATION 135+74.00 STRUCTURE NO. 038-0174