


CROSS SECTION - SPANS 1-8 & 14-17



CROSS SECTION - SPANS 9-13

TOTAL BILL OF MATERIAL

ITEM	UNIT	QUANTITY
Deck Slab Repair (Partial)	Sq. Yd.	452
Deck Slab Repair (Full Depth, Type I)	Sq. Yd.	5
Deck Slab Repair (Full Depth, Type II)	Sq. Yd.	5

GENERAL NOTES:

Only partial depth repairs are anticipated. However, nominal full depth repair quantities have been included for use in the event that removal operations break through the bottom of the deck. Therefore, the full depth areas are not called out on the patching plan sheets.

All full depth patches shall be covered by steel plates overnight, cost included in Deck Slab Repair (Full Depth).

The patch sizes and locations shown on the plan sheets are for planning purposes only. The final patch locations shall be determined by the engineer in the field.



David Carl Puzey 1/16/14
Expires 1/30/14