
JOINT REPAIR AT SOUTH ABUTMENT S.N. 020-0050


TO STA. FED. ROAD DIST. NO. | ILLINOIS | FED. AID PROJECT

*(52BR-1 & 53R-B)BJR

SHEET 6 OF 8







PROPOSED PARTIAL PLAN Joint at South Abutment

New Concrete

Concrete Removal

ILLINOIS DEPARTMENT OF TRANSPORTATION JOINT REPAIR AT SOUTH ABUTMENT

F.A.P. ROUTE 322
SECTION (52BR-1 & 53R-B)BJR
DEWITT COUNTY
S.N. 020-0050 DRAWN BY: JRP

SCALE: NA DATE: 11/06/06

BAR LIST No. Size Length

Reinforcement bars designated (E) shall

Hatched areas indicates Concrete Removal. See Sheet 7 of 8 for Proposed Joint Section. See Sheet 8 of 8 for Section Thru Parapet.

be epoxy coated.

#6 24'-0"