
JOINT REPAIR AT SOUTH ABUTMENT S.N. 020-0055


STA. TO STA. FED. ROAD DIST. NO. | ILLINOIS | FED. AID PROJECT

*(52BR-1 & 53R-B)BJR

SHEET 6 OF 7







PROPOSED PARTIAL PLAN Joint at South Abutment

BAR LIST

Bar	No.	Size	Length	Shape
a(E)	3	#6	20'-6"	
a1(E)	3	#6	25'-2"	

Reinforcement bars designated (E) shall be epoxy coated.

Hatched areas indicates Concrete Removal.

See Sheet 7 of 7 for Section Thru Parapet and Proposed Joint Section.

Concrete Removal

ILLINOIS DEPARTMENT OF TRANSPORTATION JOINT REPAIR AT SOUTH ABUTMENT

F.A.P. ROUTE 322
SECTION (52BR-1 & 53R-B)BJR
DEWITT COUNTY
S.N. 020-0055

DRAWN BY: JRP

SCALE: NA DATE: 11/08/06