

1) EXISTING GROUND (I.E., SOD, PAVEMENT, ETC.)

(2) PORTLAND CEMENT CONCRETE SIDEWALK, 5 IN

(5) EXISTING HARLEM AVENUE SUB-BASE GRANULAR MATERIAL & BITUMINOUS PAVEMENT

7 SUB-BASE GRANULAR MATERIAL, TYPE B, 4 IN (INCIDENTAL TO THE SIDEWALK)

11) FULL-DEPTH SAW CUT (INCIDENTAL TO THE BITUMINOUS CONCRETE PAVEMENT REMOVAL,

8 TOPSOIL, FURNISH AND PLACE, 4 IN
9 BITUMINOUS CONCRETE PAVEMENT REMOVAL

3 SODDING, SALT TOLERANT4 EXISTING CONCRETE CURB


(6) CONCRETE CURB, TYPE B

(FULL DEPTH)

(10) CURB REMOVAL

(FULL DEPTH))

CONTRACT NO. 83830



SECTION A-A

HARLEM AVENUE

*STA 41+29.93 TO STA 41+78.11 STA 42+06.29 TO STA 43+85.15 STA 69+97.84 TO STA 72+06.72

Globetrotters*

Engineering Corporation

ENGINEERS

ARCHITECTS

300 South Wacker Drive Chicago, Illinois 60606



Village of Bridgeview

Illinois

Steven M. Landek, Mayor

REVISIONS NAME DATE	
NAME	DATE

LEGEND

ILLINOIS DEPARTMENT OF TRANSPORTATION
SIDEWALK IMPROVEMENT
DETAIL SECTIONS

SCALE: VERT. N.T.S. HORIZ. N.T.S. DATE: 11 / 17 / 05

DRAWN BY: C.W. / K.S. CHECKED BY: C.G.