


## STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION




\* BSMART FY04-3




## NORTH ABUT. OF 044-0043 (LOOKING NORTH)




## SOUTH ABUT. OF 044-0043 (LOOKING SOUTH)



NORTH ABUT. OF 044-0044 (LOOKING NORTH)



## SOUTH ABUT. OF 044-0044 (LOOKING SOUTH)



NORTH ABUT. STRUCTURE 044-0045 (LOOKING NORTH)

6 "x1'-6" 6 "x1'	2' 4' ;;	7 7) 7 7 11	57	_1'×1'
	, , , , , , , , , , , , , , , , , , , ,	(``)	(.)	
, , ,				1
• •				
;				;

SOUTH ABUT. STRUCTURE 044-0045 (LOOKING SOUTH)

MAS
MAS
TEB
MAS

	Polymer Cement	Modified Mortar	Portland
--	-------------------	--------------------	----------

CONCRETE REPAIR
JOHNSON COUNTY
SN 044-0043
SN 044-0044
SN 044-0045