



ROUTE NO. SHEETS SHEEF NO. SHEET NO. 2 657 Henderson 14 11 5 SHEETS


Contract Number: 68774









BAR A1






BAR D







TYPICAL SECTION


12-12" \$ Strands, Each Strand Stressed to 30,900 Lbs. 8-Strands 1^3_4 " up, 4-Strands 3^l_4 " up


*** TRANSVERSE PLACEMENT GUIDELINES

- Place strands symmetrically about centerline of beam.
- 2. The minimum distance from center to center of strands in all directions shall be 2".
- 3. The minimum clearance from strand to dowel hole shall
- 4. The minimum clearance from strand to void shall be $1_2^{\prime\prime}$.

Vertical placement of strands shall not be adjusted to satisfy the above guidelines.

BEAM PLAN





LIFTING LOOP DETAIL

NOTES

Prestressing steel shall be uncoated high strength, low relaxation 7-wire strand, Grade 270. The nominal diameter shall be $\frac{1}{2}$ and the nominal cross-sectional area shall be 0.153 sq. in. Lifting loops shall be $2-\frac{1}{2}$ \$\psi \cdot 270\$ ksi strands, as shown.

The 1"\$\phi\$ rods in the transverse tie assembly shall be tightened to a snug fit and the threads set. Pockets that receive transverse tie bar on outside shall be filled with grout after transverse tie assembly is in place.

Non prestressing steel shall conform to ASTM A 706 (IL MOD), Grade 60.

The bearing seat surfaces shall be adjusted by shimming to assure firm and even bearing. Two 'B" fabric adjusting shims of the dimensions shown shall be provided for each beam,

Keyway surfaces shall be cleaned to remove form oil or other bond breaking material prior to shipment of the beams. Cleaning snall be done by sandblasting the keyway areas between top of the beam and the bottom edge of the key.

Corrosion Inhibitor, per Article 1020.05(b)(12) of the Standard Specifications, shall be used in the concrete for precast prestressed concrete deck beams.

Required Release Strength, f'ci, shall be 4000 p.s.i.

BILL OF MATERIAL

Precast Prestressed Conc. Deck Bms.	Sq. Ft.	1015

REPAIR DETAILS FA RT. 657 HENDERSON COUNTY SN 036-0038