

take appropriate precautions to deal with the presence of lead on this project.

scale, and other loose or potentially detrimental foreign material shall be removed from the surfaces in contact with concrete. Tightly adhered paint may remain unless otherwise noted. Removal shall be accomplished by methods that will not damage the steel and the cost will be included in the pay item covering removal of

construction variations. The Contractor shall field verify existing dimensions and details affecting new construction and make necessary approved adjustments prior to construction or ordering of materials. Such variations shall not be cause for additional compensation for a change in scope of the work, however, the Contractor will be paid for the quantity actually furnished based at the unit price

ITEM	UNIT	QUANTITY	
Concrete Removal	Cu. Yd.	95.1	
Concrete Superstructure	Cu. Yd.	185	
Reinforcement Bars, Epoxy Coated	Pound	30900	
Bridge Fence Railing	Foot	472	
Protective Coat	Sq. Yd.	1886	
Protective Shield	Sq. Yd.	849	
Silicone Joint Sealer, 2 ³ 4"	Foot	145	
Structural Steel Repair	Pound	1070	
Structural Repair of Concrete < 5"	Sq.Ft.	900	
Structural Repair of Concrete > 5"	Sq.Ft.	48	



EDENS EXPRESSWAY)	F.A.I. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
ELAVATION	94	2011-066-I	СООК	18	4
34			CONTRA	CT NO.6	0P85
STA. TO STA.		ILLINOIS FED.	AD PROJECT		