STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION



jeren.

ROUTE NO.	SECTION	COUNTY		TOTAL SHEETS	SHEET NO.	SHEET NO3_
5. B. I F. A. L	*	Winnebago		36	29	_8_ SHEETS
FED, ROAD DIST, NO. 7		ILLINGIS	PED. AID PPN	DJECT-		
* Sectio	n (5VE	3.5HB.	-2HB)	М	Contra	ct #64A88

BILL OF MATERIAL

ITEM	UNIT	TOTAL
Deck Slab Repair (Partial)	Sq. Yd.	80
Deck Slab Repair (Full Depth, Type 1)	Sq. Yd.	25
Deck Slab Repair (Full Depth, Type 2)	Sq. Yd.	13

Deck Survey Date: October 15, 2004

NOTES:

The plan quantities for Deck Slab Repair (Partial and Full Depth) are estimated quantities from a deck survey provided by others. The areas shown on the deck repair plans for each structure are potential areas of Deck Slab Repair. The Deck Slab Repair quantities in Bills of Material are included as contingencies to be used as directed by the engineer during construction. The actual locations and quantity of Deck Slab Repair on all structures shall be determined by the resident engineer in the field Actual repair locations shall be shown on the same as-built plans.

