



STRUCTURAL REPAIR

Cost included in Structural Repair
of Concrete (Depth < 5")

NORTH PARAPET

Looking North

Patch Number	Station	Area Sq Ft
1	27+05	2.3
2	27+38	2.3
	Total	4.6

FILE NAME =	USER NAME = swartzw	DESIGNED <i>KLB</i>	REVISED -	STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION	STRUCTURAL REPAIR - PARAPET SN. 080-0004	*5-2VB-1.5-2HB,5-2VB-2)BR-2		F.A.P. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
cr:\pw\work\pwidot\swartzw\ca0207669\077482-sht-brdetails-0800004.dgn		DRAWN <i>KLB</i>	REVISED -			327	.	Richland	53	26		
PLOT SCALE = 20.0000 ' / IN.		CHECKED <i>MEA</i>	REVISED -			CONTRACT NO. 74482		ILLINOIS FED. AID PROJECT				
PLOT DATE = 1/27/2011		DATE <i>12/2/10</i>	REVISED -			SCALE: NA	SHEET NO. 5 OF 15 SHEETS	STA.	TO STA.			