STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION

INDEX OF SHEETS

- 1 Title Sheet
- Index of Sheets, State Standards, General Notes and Summary of Quantities 2
- 3-4 Maintenance of Traffic
- 5.10 Structure Plans S1-S6
- 11-13 District One Standards
 - Highway Standards

INDEX OF HIGHWAY STANDARDS

Standard No.	Description
000001 - 05	Standard Symbols. Abbreviations And Patterns
001001 - 02	Areas Of Reinforcement Rebars
420001 - 07	Pavement Joints
701301 - 03	Lane Closure, 2L, 2W, Short Time Operations
701306 - 02	Lane Closure, 2L, 2W, Slow Moving Operations, Day Only
701321 - 1 0	Lane Closure, 2L, 2W, Bridge Repair with Barrier
701501 - 05	Urban Lane Closure, 2L, 2W, Undivided
701502 - 03	Urban Lane Closure, 2L, 2W, Bidirectional Left Turn
70 <i>1</i> 602 - 04	Urban Lane Closure, Multilane 2W, Bidirectional Left Turn
701606 - 06	Urban Lane Closure, Multilane 2W, with Mountable Median
701901 - 01	Traffic Control Devices
704001 -06	Temporary Concrete Barrier
780001 - 02 '	Typical Pavement Markings
781001 - 03	Typical Applications Raised Reflective Pavement Markers
701400-04	
701401-05	
701446-01	

GENERAL NOTES

- These plans have been prepared from notes received from IDOT Field Maintenance Engineers.
- 2. 10 ft (3 m) transitions shall be used to match proposed items of work to existing ilems in the field, unless otherwise shown. The transitions shall be paid for at the contract unit price for the proposed item of work specified.
- 3. Where artificial lighting is utilized in night operations, the Contractor shall exercise the utmost precautions in preventing adverse visibility to the motoring public and adioinina residential areas.
- 4. The engineer shall be the sole judge concerning curing time for the various hot-mix asphalt lifts.
- 5. For stabilization, all Type III barricades shall require a minimum of four (4) sandbags per barricade.
- 6. The Resident Engineer must contact the Traffic Control Supervisor at (847)705-4470 at least 72 hours prior to installation of the temporary control devices.
- 7. The Resident Engineer shall contact the CDOT Area Traffic Field Engineer at at least two (2) weeks prior to the placement of permanent pavement markings.
- 8. All pavement markings and raised reflectors affected by the bridge repairs shall be replaced. Nominal quantities have been included in the contract for this work.
- 9. The Contractor will not be allowed to set up a yard or field office on State property without written permission from the Department.
- 10. Do not scale these plans for construction purposes.
- 11. Plan dimensions and details relative to existing plans are subject to routine variations. The Contractor shall field verify existing dimensions and details affecting new construction and make necessary approved adjustments prior to construction or ordering of materials. Such variations shall not be cause for additional compensation for shange in scope of the work. However, the Contractor will be paid for the nuartity actually furnished based upon the unit price bid for the work.

- 12, During construction operations, loose material deposits that obstruct the flow of water in draining the area shall be removed before the end of each work day. At the conclusion of construction operations, all drainage structures (new and existing) shall be free from all dirt and debris. This work will not be paid for separately but shall be considered incidental to the contract.
- 13. All Type 1 and Type II barricades shall have two (2) sandbags on the bottom rall.
- 14. All raised reflective pavement markers (bridge) shall be low profile.
- 15. Special attention is called to Article 107.12 regarding railroad flaggers. The name and telephone number of the railroad engineer is Mr. David Heard (312) 681-3862.
- 16. Before beginning any work, the Contractor shall retain and record for future reference, all existing pavement marking lines, symbols and letters (and raised reflective markers) in order that these locations can be re-established for striping. Exact locations of all pavement markings and raised reflective pavement markers shall be as directed by the Engineer. shall be as directed by the Engineer.

CODE ITEM DESCRIPTION 50157301 Protective Shield (Permanent) 67000400 Engineer's Field Office, Type A 67100100 Mobilization 70101800 Traffic Control and Protection, (Special) 7030100 Work Zone Pavement Marking Removal 70400100 Temporary Concrete Barrier * 78000200 Relocate Temporary Concrete Barrier * 78000200 Raised Reflective Pavement Marking, Type I - Line 4" * 78100100 Raised Reflective Pavement Marker * 78100200 Raised Reflective Pavement Marker (Bridge) 78300100 Pavement Marking Removal 78300100 Raised Reflective Pavement Marker (Bridge) 78300100 Raised Reflective Pavement Marker Removal x0320200 Raised Reflective Pavement Marker I x0321743 Silicone Joint Sedier, 2.* x0321744 Silicone Joint Sedier, 2.* x0322565 Temporary Information Signing x03225775 Wet Reflective Temporary Tape, Type III, 4 Inch Z0006020 Deck Slab Repair (Full Deuth, T		
67000400Engineer's Field Office, Type A67100100Mobilization70101800Traffic Control and Protection, (Special)70301000Work Zone Pavement Marking Removal70400100Temporary Concrete Barrier70400200Relocate Temporary Concrete Barrier*78000200Relocate Temporary Concrete Barrier*78008210Polyurea Pavement Marking, Type I - Line 4"*78100100Raised Reflective Pavement Marker*78100100Raised Reflective Pavement Marker78300100Pavement Marking Removal78300200Raised Reflective Pavement Marker (Bridge)78100200Temporary Raised Reflective Pavement Marker78300200Raised Reflective Pavement Marker RemovalX0320887Polymer ConcreteX0321743Silicone Joint Sealer, 1"X0322256Temporary Information SigningX0322575Wet Reflective Temporary Tape, Type III, 4 InchZ0016002Deck Slab Repair (Full Depth, Type II)Z0030250Impact Attenuators, Temporary (iwn-Redirective), TestZ0030350Impact Attenuators, Relocate (Non Redirective), Test LZ0048665Railroad Protective 'Lability InsuranceZ00746600TraincesX17011015Traffic Control and Protection (Express& Totilo15Traffic Control and Protection (Express& Totilo15Traffic Control and Protection (Express& Totilo15Traffic Control and Protection (Express	CODE	ITEM DESCRIPTION
67100100 Mobilization 70101800 Traffic Control and Protection, (Special) 70301000 Work Zone Pavement Marking Removal 70400100 Temporary Concrete Barrier 70400200 Relocate Temporary Concrete Barrier * 78000200 Thermoplastic Pavement Marking, Type I - Line 4" * 78000200 Thermoplastic Pavement Marking, Type I - Line 4" * 78008210 Polyurea Pavement Marking, Type I - Line 4" * 78100100 Raised Reflective Pavement Marker * 78100105 Raised Reflective Pavement Marker * 78100200 Temporary Raised Reflective Pavement Marker 78300100 Povement Marking Removal Raised Reflective Pavement Marker Removal 78300200 Raised Reflective Pavement Marker Removal X0320887 70/ymer Concrete X0321743 Silicone Joint Sealer, 1" X03221744 X0322256 Temporary Information Signing X0322233 Silicone Joint Sealer, 2.5" X0322775 Wet Reflective Temporary Tape, Type III, 4 Inch Z0016002 Deck Slab Repair, (Partial) Z0016002 Deck Slab Repair, (Partial) Z0030350 Impact Attenuators, Remocade (Non Redirectiv	50157301	Protective Shield (Permanent)
70101800 Traffic Control and Protection, (Special) 70301000 Work Zone Pavement Marking Removal 70400100 Temporary Concrete Barrier 70400200 Relocate Temporary Concrete Barrier * 78000200 Thermoplastic Pavement Marking - Line 4" * 78000200 Relocate Temporary Concrete Barrier * 78000200 Thermoplastic Pavement Marking - Line 4" * 78000200 Raised Reflective Pavement Marker * 78100105 Raised Reflective Pavement Marker (Bridge) 78100200 Temporary Raised Reflective Pavement Marker 78300100 Povement Marking Removal 78300200 Raised Reflective Pavement Marker Removal 70321743 Silicone Joint Sealer, 1" X0320887 Polymer Concrete X0321744 Silicone Joint Sealer, 2.5" X0322256 Temporary Information Signing X03222575 Wet Reflective Temporary Tape, Type III, 4 Inch Z0016002 Deck Slab Repair (Full Depth, Type II) Z0016002 Deck Slab Repair, (Partial) Z0030350 Impact Attenuators, Relocate (Non Redirective)	67000400	Engineer's Field Office, Type A
70301000 Work Zone Pavement Marking Removal 70400100 Temporary Concrete Barrier 70400200 Relocate Temporary Concrete Barrier * 78000200 Thermoplastic Pavement Marking - Line 4" * 78008210 Polyurea Pavement Marking, Type I - Line 4" * 78100100 Raised Reflective Pavement Marker * 78100105 Raised Reflective Pavement Marker * 78100105 Raised Reflective Pavement Marker (Bridge) 78100200 Temporary Raised Reflective Pavement Marker 78300200 Raised Reflective Pavement Marker Removal 78302200 Raised Reflective Pavement Marker Removal 70322030 Raised Reflective Pavement Marker Removal 703221743 Silicone Joint Sealer, 2" 70322255 Temporary Information Signing 70325775 Wet Reflective Temporary Tape, Type III, 4 Inch 20016002 Deck Slab Repair, (Partial) 20030	67100100	Mobilization
70400100 Temporary Concrete Barrier 70400200 Relocate Temporary Concrete Barrier * 78000200 Thermoplastic Pavement Marking - Line 4" * 78008210 Polyurea Pavement Marking, Type I - Line 4" * 78100100 Raised Reflective Pavement Marker * 78100105 Raised Reflective Pavement Marker * 78100105 Raised Reflective Pavement Marker * 78100100 Temporary Raised Reflective Pavement Marker 78300200 Temporary Raised Reflective Pavement Marker 78300200 Raised Reflective Pavement Marker Removal X0320887 Polymer Concrete X0321743 Silicone Joint Sealer, 1" X03221743 Silicone Joint Sealer, 2" X0322256 Temporary Information Signing X0322253 Silicone Joint Sealer, 2.5" X0325775 Wet Reflective Temporary Tape, Type III, 4 Inch Z0016002 Deck Slab Repair, (Partial) Z0030250 Impact Attenuators, Temporary (iwn-Redirective), Test Z0030350 Impact Attenuators, Relocate (Non Redirective), Test Z0048665 Railroad Protective 'Liability Insurance Z00746600	70101800	Traffic Control and Protection, (Special)
70400200 Relocate Temporary Concrete Barrier * 78000200 Thermoplastic Pavement Marking - Line 4" * 78008210 Polyurea Pavement Marking, Type I - Line 4" * 78100100 Raised Reflective Pavement Marker * 78100105 Raised Reflective Pavement Marker * 78100105 Raised Reflective Pavement Marker * 78100100 Temporary Raised Reflective Pavement Marker 78300100 Pavement Marking Removal 78300200 Raised Reflective Pavement Marker Removal 78302200 Raised Reflective Pavement Marker Removal 78302200 Raised Reflective Pavement Marker Removal 78322285 Silicone Joint Sealer, 1" 70322256 Temporary Information Signing 70325775 Wet Reflective Temporary Tape, Type III, 4 Inch 20016002 Deck Slab Repair. (Partial)	70301000	Work Zone Pavement Marking Removal
 * 78000200 Thermoplastic Pavement Marking - Line 4" * 78008210 Polyurea Pavement Marking, Type I - Line 4" * 78100100 Raised Reflective Pavement Marker * 78100105 Raised Reflective Pavement Marker * 78100105 Raised Reflective Pavement Marker (Bridge) 78100100 Temporary Raised Reflective Pavement Marker 78300100 Pavement Marking Removal 78300200 Raised Reflective Pavement Marker Removal 783022087 Polymer Concrete 70321743 Silicone Joint Sealer, 1" 70322744 Silicone Joint Sealer, 2" 70322256 Temporary Information Signing 70322256 Temporary Information Signing 70325775 Wet Reflective Temporary Tape, Type III, 4 Inch 20016002 Deck Slab Repair (Full Dcpth, Type II) 20016200 Impact Attenuators, Temporary (ivon Redirective), Test 20030350 Impact Attenuators, Relocate (Non Redirective), Test 20030350 Impact Attenuators, Relocate (Non Redirective), Test L 200746600 TrainceS X1011015 Traffic Control and Protection (Express 85000300 Maintscaance of Existing Traffic Signing 	70400100	Temporary Concrete Barrier
* 78000200 Thermopolatic Foreign working Life 4 * 78008210 Polyurea Pavement Marking, Type I - Line 4" * 78100100 Raised Reflective Pavement Marker * 78100105 Raised Reflective Pavement Marker * 78100100 Temporary Raised Reflective Pavement Marker 78100100 Pavement Marking Removal 78300100 Pavement Marking Removal 78300200 Raised Reflective Pavement Marker Removal 70320887 Polymer Concrete X0321744 Silicone Joint Sealer, 1" X0322256 Temporary Information Signing X0325775 Wet Reflective Temporary Tape, Type III, 4 Inch 20016002 Deck Slab Repair, (Partial) 20030250 Impact Attenuators, Temporary (won Redirective), Test L 200	70400200	Relocate Temporary Concrete Barrier
 * 78/00/00 Raised Reflective Pavement Marker * 78/00/00 Raised Reflective Pavement Marker * 78/00/05 Raised Reflective Pavement Marker (Bridge) 78/00/00 Temporary Raised Reflective Pavement Marker 78/00/00 Pavement Marking Removal 78/00/00 Raised Reflective Pavement Marker Removal 78/00/00 	* 78000200	Thermoplastic Pavement Marking - Line 4"
* 78100100 Raised Reflective Pavement Marker * 78100105 Raised Reflective Pavement Marker (Bridge) 78100200 Temporary Raised Reflective Pavement Marker 78300100 Pavement Marking Removal 78300200 Raised Reflective Pavement Marker Removal 78300200 Raised Reflective Pavement Marker Removal 78300200 Raised Reflective Pavement Marker Removal X0320887 Polymer Concrete X0321743 Silicone Joint Sealer, 1" X0322743 Silicone Joint Sealer, 2" X0322256 Temporary Information Signing X0322933 Silicone Joint Sealer, 2.5" X03225775 Wet Reflective Temporary Tape, Type III, 4 Inch Z0016002 Deck Slab Repair (Full Depth, Type II) Z0016200 Deck Slab Repair, (Partial) Z0030250 Impact Attenuators, Temporary (Won-Redirective), Test Z0030350 Impact Attenuators, Relocate (Non Redirective), Test L Z0048665 Railroad Protective Liability Insurance Z00746600 Trainces X1011015 Treffic Control Ond Protection (Express & \$2003030 Maintenance of Existing Traffic Sign	70000210	Polyurea Pavement Marking, Type I - Line 4"
78100303 Tenporary Raised Reflective Pavement Marker 78100200 Temporary Raised Reflective Pavement Marker 78300100 Pavement Marking Removal 78300200 Raised Reflective Pavement Marker Removal 78320887 Polymer Concrete 70321743 Silicone Joint Sedler, 1" 70322256 Temporary Information Signing 70325775 Wet Reflective Temporary Tape, Type III, 4 Inch 20016002 Deck Slab Repair, (Partial) 20016200 Deck Slab Repair, (Partial) 20030250 Impact Attenuators, Temporary (ivon-Redirective), Test L 20030350 Impact Attenuators, Relocate (Non Redirective), Test L 200746600 Troinces X1011015 Troeffic Control and Protection (Express 85000300 Maintenance of Existing Traffic Signific	* 78100100	Raised Reflective Pavement Marker
78300100 Pavement Marking Removal 78300200 Raised Reflective Pavement Marker Removal X0320887 Palymer Concrete X0321743 Silicone Joint Sealer, 1" X0321744 Silicone Joint Sealer, 2" X0322256 Temporary Information Signing X03222575 Wet Reflective Temporary Tape, Type III, 4 Inch Z0016002 Deck Slab Repair (Full Depth, Type II) Z0030250 Impact Attenuators, Temporary (Non-Redirective), Test Z0030350 Impact Attenuators, Relocate (Non Redirective), Test L Z0048665 Railroad Protective Liability Insurance Z007/66/20 TroinceS X1011015 Troeffic Control and Protection (Express 85000300 Maintsnance of Existing Traffic Signity	* 78100105	Raised Reflective Pavement Marker (Bridge)
78300200 Raised Reflective Pavement Marker Removal X0320887 Polymer Concrete X0321743 Silicone Joint Sealer, 1" X0321743 Silicone Joint Sealer, 2" X0322744 Silicone Joint Sealer, 2." X03228256 Temporary Information Signing X0322933 Silicone Joint Sealer, 2.5" X0325775 Wet Reflective Temporary Tape, Type III, 4 Inch Z0016002 Deck Slab Repair (Full Depth, Type II) Z0016200 Deck Slab Repair, (Partial) Z0030250 Impact Attenuators, Temporary (ivon-Redirective), Test Z0030350 Impact Attenuators, Relocate (Non Redirective), Test Z0048665 Railroad Protective Liability Insurance Z0076600 TrainceS X1011015 Troeffic Control and Protection (Express 85000300 Maintsnance of Existing Traffic Sign	78100200	Temporary Raised Reflective Pavement Marker
X0320887 Polymer Concrete X0321743 Silicone Joint Sealer, 1" X0321743 Silicone Joint Sealer, 2" X0322256 Temporary Information Signing X03222933 Silicone Joint Sealer, 2.5" X03225775 Wet Reflective Temporary Tape, Type III, 4 Inch Z0016002 Deck Slab Repair (Full Depth, Type II) Z0016200 Deck Slab Repair, (Partial) Z0030250 Impact Attenuators, Temporary (won-Redirective), Test Z0030350 Impact Attenuators, Relocate (Non Redirective), Test Z00746600 TrainceS X1011015 Trooffic Control and Protection (Express 85000300 Maintsnance of Existing Traffic Signing	78300100	Pavement Marking Removal
X0321743 Silicone Joint Sedler, I" X0321744 Silicone Joint Sedler, 2" X0322256 Temporary Information Signing X03222933 Silicone Joint Sedler, 2.5" X0325775 Wet Reflective Temporary Tape, Type III, 4 Inch Z0016002 Deck Slab Repair (Full Deµth, Type II) Z0016200 Deck Slab Repair, (Partial) Z0030250 Impact Attenuators, Temporary (iwn-Redirective), Test Z0048665 Railroad Protective Liability Insurance Z0076600 Trainces X0076600 Maintenance of Existing Traffic Signame	78300200	Raised Reflective Pavement Marker Removal
X0321744 Silicone Joint Sealer, 2" X0322256 Temporary Information Signing X03222933 Silicone Joint Sealer, 2.5" X0325775 Wet Reflective Temporary Tape, Type III, 4 Inch Z0016002 Deck Slab Repair (Full Depth, Type II) Z0016200 Deck Slab Repair, (Partial) Z0030250 Impact Attenuators, Temporary (Non-Redirective), Test Z0030350 Impact Attenuators, Relocate (Non Redirective), Test Z0048665 Railroad Protective Liability Insurance Z0076600 TroinceS X1011015 Troffic Control and Protection (Express 85000300 Maintenance of Existing Traffic Signital	X0320887	Polymer Concrete
X0322256 Temporary Information Signing X0322933 Silicone Joint Sedler, 2.5" X0325775 Wet Reflective Temporary Tape, Type III, 4 Inch Z0016002 Deck Slab Repair (Full Depth, Type II) Z0016200 Deck Slab Repair, (Partial) Z0030250 Impact Attenuators, Temporary (Kon-Redirective), Test Z0030350 Impact Attenuators, Relocate (Non Redirective), Test Z0048665 Railroad Protective Liability Insurance Z0076600 TrainceS X1011015 Traffic Control and Protection (Express 85000300 Maintenance of Existing Traffic Signitic	X0321743	Silicone Joint Sealer, 1"
X0322933 Silicone Joint Seder, 2.5" X0325775 Wet Reflective Temporary Tape, Type III, 4 Inch Z0016002 Deck Slab Repair (Full Depth, Type II) Z0016200 Deck Slab Repair, (Partial) Z0030250 Impact Attenuators, Temporary (Wun-Reditective), Test Z0030350 Impact Attenuators, Relocate (Non Reditective), Test Z0048665 Railroad Protective Liability Insurance Z0076600 TrainceS X1011015 Traffic Control and Protection (Express 85000300 Maintenance of Existing Traffic Signature	X0321744	Silicone Joint Sealer, 2"
X0325775 Wet Reflective Temporary Tape, Type III, 4 Inch Z0016002 Deck Slab Repair (Full Depth, Type II) Z0016200 Deck Slab Repair, (Partial) Z0030250 Impact Attenuators, Temporary (iion-Redirective), Test Z0030350 Impact Attenuators, Relocate (Nan Redirective), Test L Z0048665 Railroad Protective Liability Insurance Z0076600 TrainceS X7011015 Traffic Control and Protection (Express B5000300 Maintenance of Existing Traffic Sig	X0322256	Temporary Information Signing
Z0016002 Deck Slab Repair (Full Depth, Type II) Z0016200 Deck Slab Repair, (Partial) Z0030250 Impact Attenuators, Temporary (Non-Redirective), Test Z0030350 Impact Attenuators, Relocate (Non Redirective), Test L Z0048665 Railroad Protective Liability Insurance Z0076600 Traince5 X7011015 Traffic Control and Protection (Express 65000300 Maintenance of Existing Traffic Signature	X0322933	Silicone Joint Sealer, 2.5"
Z0016200 Deck Slab Repair, (Partial) Z0030250 Impact Attenuators, Temporary (Non-Redirective), Test Z0030350 Impact Attenuators, Relocate (Non Redirective), Test L Z0048665 Railroad Protective Liability Insurance Z0076600 Trainces X1011015 Traffic Control and Protection (Express 85000300 Maintenance of Existing Traffic Signature	X0325775	Wet Reflective Temporary Tape, Type III, 4 Inch
Z0030250 Impact Attenuators, Temporary (Non-Redirective), Test Z0030350 Impact Attenuators, Relocate (Non Redirective), Test L Z0048665 Ralitroad Protective Liability Insurance Z0076600 Traince5 X7011015 Traffic Control and Protection (Express B5000300 Maintenance of Existing Traffic Signature	Z0016002	Deck Slab Repair (Full Depth, Type II)
Z0030350Impact Attenuators, Relocate (Nan Redirective), Test LZ0048665Railroad Protective Liability InsuranceZ0076600TraincesX7011015Traffic Control and Protection (ExpressB5000300Maintenance of Existing Traffic Signature	Z0016200	Deck Slab Repair, (Partial)
20048665 Railroad Protective Liability Insurance 20076600 Trainces X7011015 Traffic Control and Protection (Expres 85000300 Maintenance of Existing Traffic Sig	Z0030250	Impact Attenuators, Temporary (Nun-Redirective), Test
20076600 Trainces X7011015 Traffic Control and Protection (Expres 85000300 Maintenance of Existing Traffic Sig	Z0030350	Impact Attenuators, Relocate (Non Redirective), Test L
X7011015 Traffic Control and Protection (Expres 85000300 Maintenance of Existing Traffic Sig	Z0048665	Railroad Protective Liability Insurance
85000300 Maintenance of Existing Traffic Si	20076600	Trainces
	X7011015	Traffic Control and Protection (Expres
X0325737 Temporary Traffix Signal Timir	85000300	Maintenance of Existing Traffic Sig
	X0325737	Temporary Traffiz Signal Timin
		en e
		3
	and the second	
		1

FILE NAME : D160J69:shtigernote.dgn	USER NAME == IDititiong)	DESIGNED J. DRAWN D	.W. KOONCE REDZIC	REVISED - REVISED -	STATE OF ILLINUIS	INDEX OF SHEET	S, STATE STANDAI FAU 2729	IDS, GENERAL EAST RIVER R	
	PLOT SCALE = 120000 17 IN. PLOT SATE = 27572012	DATE - J.	ANUARY, 2010	REVISED -	DEPARTMENT OF TRANSPORTATION	SCALE:	SHEET NO. 1 (F 1 SHEETS	STA.

	QUANTITIES	<u>,</u>	URBAN CONSTR. TO TOT
			STRUCTUR X281-2A
	UNIT	QUANTITY	
	Sq.Yd.	11238	1,238
	Cal.M o	2	
	L SUM	t /	
	LISUM	1	· · · · · · · · · · · · · · · · · · ·
	Sq. FT	860	860
	Fo	860	560
	Fea	860	860
	Foot	270	270
	Foot	670	670
	Each	10	
	Each	10	10
	Each	10	10
	Sq.Ft.	310	310
	Each	10	10
	Cu.Ft.	27.8	27.8
	Foot	254.4	254.4
	Foot	63.6	63.6
	Sq.Ft.	50	50
	Foot	63.6	63.6
	Foot	2,600	2,600
	Sq.Yd.	16.0	<i>16.0</i>
	Sq.Yd.	117.3	//7.3
est Level 3	Each	2	2
st Level 3	Each	2	
	L: Sum	1	
	Hour	500	500
	LSum		1
rescuars)			
	1 5	/	1
Signal Installation	LSum	/	0
Signal Installation	L Sum Each	2	2
Signal Installation			2
ressways) Signal Installation ning			
Signal Installation	Each		