
## SUBSTRUCTURE REPAIR DETAIL SN 098-0052 SOUTH ABUTMENT (LOOKING SOUTH)



SN 098-0052 SOUTH ABUTMENT (LOOKING SOUTH)

1	ITEM	QUANTITY
	(*) STRUCTURAL REPAIR OF CONCRETE =< 5"	41.5 (SQ FT)
	(*) STRUCTURAL REPAIR OF CONCRETE > 5"	8.0 (SQ FT)
£		

(\*) THIS IS AN ESTIMATED QUANTITY. THE ACTUAL LOCATION OF DELAMINATED AREAS AND QUANTITIES WILL BE DETERMINED BY THE RESIDENT ENGINEER IN THE FIELD.

J TEMPORARY SHORING AND CRIBBING
DELAMINATED AREA > 5"
DELAMINATED AREA =< 5"</p>

File NAME : USER NAME : dosadd DESIGNED - REVISED 5/28/2014 DDD

Qi/BR\Qosa\Whiteside\64J92 Repairs SN 8/8-8851 & SN 898-8852\CADO\0287713\*ahtroove - DRAWN - REVISED 
PLOT SCALE + 100.8088 '/ in. CHECKED - REVISED 
Oefoult PLOT DATE + Ned May 28 86:5813 2014 DATE - REVISED -

STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION

SUBSTRUCTURE REPAIR DETAIL

SN 098-0052 SOUTH ABUTMENT (LOOKING SOUTH)

SHEET OF SHEETS STA. TO STA.

FAU. SECTION COUNTY SHEET NO. 5571 D2 BRIDGE REPAIR 2014-2 WHITESIDE 33 10

CONTRACT NO. 64J92