






BENT 2
(Looking East)



BILL OF MATERIAL

Item	Unit	Total
Structural Steel Repair	Pound	850

Note A:
Field drill holes using existing holes as template.
Remainder of holes may be shop or field drilled.

Note:
All bolted connections shown on this sheet shall be made with $\frac{3}{4}$ " dia. H.S. bolts.



USER NAME =
DESIGNED - ZJB
CHECKED - YSS
PLOT SCALE =
DRAWN - AEC
PLOT DATE = 03/20/2014
CHECKED - ZJB
REVISED

DESIGNED - ZJB
CHECKED - YSS
DRAWN - AEC
CHECKED - ZJB
REVISED

DESIGNED - ZJB
CHECKED - YSS
DRAWN - AEC
CHECKED - ZJB
REVISED

STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION

MISSOURI APPROACH BENT 2 REPAIRS
S.N. 082-6001 MLK BRIDGE OVER MISSISSIPPI RIVER

SHEET NO. S108 OF S138 SHEETS

F.A.P. R.T.E.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
799	IBR, DRS-2	ST. CLAIR	156	126
CONTRACT NO. 76B03				
ILLINOIS FED. AID PROJECT				