

Notes:

Replace Hanger

Replace Fastener

Realign Downspout

Reconnect Drain Pipe

*Unclog Drain

Reconnect Drain Pipe

*Unclog Drain

Tighten Bolt

*Unclog Drain

Repair of the existing drainage system shall include but may not be limited to the locations shown. The final repair locations will be determined by the Engineer prior to repair.

All work shown on this sheet shall be included in pay item Bridge Drainage System Repair unless noted otherwise.

In addition to the repairs shown on this sheet, the drainage system for the entire bridge including scuppers, floor drains and downspouts shall be cleaned. Cost included with Cleaning Drainage System.

		USER NAME =	DESIGNED – JJA	REVISED -	
		FILE NHME -	CHECKED - TBP	REVISED -	STATE OF ILLINOIS
	Consulting Engine Springfield, Illinois	PLOT SCALE =	DRAWN - AJF	REVISED -	DEPARTMENT OF TRANSPORTATION
	Springheid, minois	PLOT DATE = 05/02/2014	CHECKED - VPT	REVISED -	

Missing Fastener on Drain Pipe Support

Drain Downspout Misaligned

Drain Pipe is Disconnected

Clogged, Full of Debris

Broken Drain

Clogged, Full of Debris

1 Loose Bolt in Drain Connection

Clogged, Full of Debris

72

100

144

305

305

309

368

369

372

9

W

9

31. 32

31, 32

4

W

9

Pan. 8, N. & S. Side

Under Stringer 5 at Bent W

Between L7 & L8, N. Side

North Column of Bent 31

North Column of Bent 31

20' from Bent 3 at Girder 1

Throughout South Side

Throughout South Side

1, 2 North Column, 6' from Ground Level

DRAINAGE REPAIR S.N. 082-6001 MLK BRIDGE OV SHEET NO. S128 OF S

BILL OF MATERIAL

Item	Unit	Total		
Bridge Drainage System Repair	Each	10		
Cleaning Drainage System	L Sum	1		

IR DETAILS		F.A.P. SECTION			COUNTY TOTAL SHEE SHEETS NO			
VER MISSISSIPPI RIVER	799	1BR, [1BR, DRS-2		ST.	CLAIR	156	146
					CON	TRACT	NO. 7	6B03
S138 SHEETS	ILLINOIS FED. AID				D PROJE	СТ		