

SECTION THRU POST ABOVE LOWER CHORDS

- (2) After tightening lower connection bolts, fill gap with non-hardening, silicone caulk suitable for exterior exposure and acceptable to the Engineer. Cost is included in Overhead Sign Structure Cantilever.
- (3) Upper and lower connection bolts in collar and bolts at lower chord connection shall be high strength with matching locknuts. Connection

s	– JUNCTURE DETAILS		F.A.I. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.	
& STEEL POST		90/94	0303-474HB-R	СООК	368	150		
x SILLE FUSI					CONTRACT	NO. 6	OF63	
S	STA.	TO STA.	FED. RC	FED. ROAD DIST. NO. 1 ILLINOIS FED. AID PROJECT				